97714C	447		FY 2024 BC Software R2P2
12350VC	447	97714C	Release created to enable PGN 57344 on 250K Body Builder Datalink
15372VC	447	97714C	Release created to support changes for Drain valve heating feature
15373VC	447	97714C	Release created to make feature 0597383 compatible with CE Bus wing panel and CE Bus flat panel
15792VC	447	97714C	Release Created to open 597240, 597431, 597114, 597685 for IP
15828VC	447	97714C	Fix issues with signal units for EV based HVAC
15836VC	447	97714C	Release created to be able to remove Cruise control dependency for 6xx ebus
15843VC	447	97714C	Release created to update default parameter value and range of Standstill time threshold for HSA

• Database 447 Release date 11/06/2024

• Database 446 Release date 11/05/2024

97314T	446		2024 R2 Parent Release
13538VC	446	97314T	To update FMI for loss of comm between SDP and BCM
13693VC	446	97314T	Created a release To update extended Electric Horn Chirp function activation time to 500ms
14051VC	446	97314T	To create new External Regen Alarm feature
14841VC	446	97314T	Release created for Hood Badge Lamp
15082VC	446	97314T	632 OP Update
15187VC	446	97314T	Added 0597760 to support Trailer Detection feature after adding SPN 523777 in LLSW
15334VC	446	97314T	Electric Door Motor Calibration by Button Dance. Hazard Switch and High Beam Switch
15443VC	446	97314T	Release created to send speaker faulted popup request to EGC when speaker has error or Radio and BCM has loss of comm
15449VC	446	97314T	747 OP Update
15501VC	446	97314T	Release created to broadcast vehicle architecture msg
15504VC	446	97314T	Release created to request Force/Hold Neutral for T14 transmission

• Database 445 Release date 10/29/2024

ER_2024_1	445		Emergency Release to correct Penske field issue
16247VC	445	ER_2024_1	Disable Ch2 on 250K PT for PGN 65274

• Database 444 Release date 10/16/2024

DLBFR_2024_5	444		Filter rule updates
16203VC	444	DLBFR_2024_5	Release Created to open 597472, 597718, 597736 for MV, HV, HX, IP

• Database 443 Release date 10/01/2024

DLBFR_2024_	443		Parent DLBFR release		
DLBFR748	443	DLBFR_2024_	Correct error with filter rule 0597748		

• Database 442 Release date 09/24/2024

97714D	442		FY 2024 BC Software R2P3
15806VC	442	97714D	E79 BCM ELC with Auto Headlights
15915VC	442	97714D	Release created to remove the effect of PWL flasher switch on red PWLs

• Database 441 Release date 09/11/2024

97618V	441		2024 R1p11 Parent Release
15081VC	441	97618V	OP 746
15638VC	441	97618V	HydroCarbon Desorb Mode update to Auto Start-Stop (Regen)
15927VC	441	97618V	Release to enable Master Flasher Off Pop Up Message

• Database 440 Release Date: 08/19/2024

DLBFR 2024 3	440		Add features for H08 Cert builds to allow configuration to be built
<u>16052VC</u>	440	DLBFR_2024_3	Add 0597692 IP to 0597770 to allow features in configuration

Diamond Logic Builder Update to 15924 (Release Date: 7/23/2024)

- Add 0597054 to script for calibrating Trailer Lamps
- Update to Horizon Premium Cluster Flash Loader
- Horizon R1_2024 cluster software
- Horizon R2_2024 cluster software
- Block V26 => V25 Switch Pack downgrade
- EV cluster R3 software release
- Compatibility check: ESC Kernel 745 and EV Cluster Kernel 05.09.08

Release	Database	Parent	Description
<u>97618M</u>	439		BCM_R1p9_2024_EXT
<u>15511VC</u>	439	<u>97618M</u>	New Bus: PP update for the lift door flash indicator
<u>15512VC</u>	439	<u>97618M</u>	Release created to add Pp to control PTI features
15526VC	439	<u>97618M</u>	Initial Creation for Crossing gate update for MFSAB(Multi-Function School Activity Bus)
	439	<u>97618M</u>	Release created to update emergency exit feature codes to activate all the dome lights
<u>15548VC</u>			except driver dome lights should be off
<u>15807VC</u>	439	<u>97618M</u>	Release created to set Dome Light 3X flashing for Post Trip Inspection Disarm state.

• Database 439 (Release Date: 8/9/2024)

• Database 438 (Release Date: 8/08/2024)

DLBFR 2024 2	438		To create new feature code for PP override similar to 0595AZJ
<u>15998VC</u>	438	DLBFR_2024_2	Open up 0597584 to 0597773 for electric bus

• Database 437 (Release Date: 8/04/2024)

_						
	97618L	437		FY 2024 BC Software R1P8		

<u>15765VC</u>	437	<u>97618L</u>	Create new ePower feature(ePTO vs ePower change)
<u>15874VC</u>	437	<u>97618L</u>	Release for updating PWL Red Override for Momentary switch
<u>9128VC</u>	437	<u>97618L</u>	To create new feature code for PP override similar to 0595AZJ

Database 436 (Release Date: 7/25/2024)

97314M 436 Cluster flashl	oader and Cluster release R2p2_2024

• Database 435 (Release Date: 7/25/2024)

97618K	435		2024 R1p7 Parent Release
14764VC	435	<u>97618K</u>	Release created to add eMV IP 0597552 to Steering wheel DLB switches
14765VC	435	<u>97618K</u>	Release created to open cruise control on central panel 0597528 feature code for eMV
<u>14916VC</u>	435	<u>97618K</u>	Release created to open feature codes for eMV configuration.
15510VC	435	<u>97618K</u>	To create new IP for eMV Wing panel.

•						
Database 434 (Release Date: 7/25/2024)						
15516VC	434		OP 745 Update			
•						
<u>97618G</u>	433		EV Cluster 5.09.08			

• Database 432 (Release Date: 7/22/2024)

<u>97618R</u>	432		2024 R1p10 Parent Release		
15935VC	432	<u>97618R</u>	Release to update 5Th Wheel Jaw Unlock Control		

Diamond Logic Builder Update to 15888 (Release Date: 6/12/2024)

• Support for Love's Single Sign On.

Diamond Logic Builder Update to 15887 (Release Date: 3/12/2024)

• Licensing update.

• Database 431 (Release Date: 7/2/2024)

DLBFR 2024 02	431		Remove Carriage return from cluster display for 0597758 Lane Keep Assist
DLB2024_2	431	DLBFR 2024 02	Remove Carriage return from cluster display for 0597758 Lane Keep Assist

• Database 430 (Release Date: 6/26/2024)

<u>97513E</u>	430		2024 R1p4 Release
<u>15527VC</u>	430	<u>97513E</u>	Release created to open 0597271 for M-CE
			Release created for NFC for 5 speed transmission with park pawl and no shifter interlock
<u>15764VC</u>	430	<u>97513E</u>	solenoid

• Database 429 (Release Date: 6/12/2024)

<u>973145</u>	429		2024 R1p1 Parent Release	
<u>14991VC</u>	429	<u>97314S</u>	Update Auto re-enable time PP value for Lane departure warning features.	
<u>14993VC</u>	429	<u>97314S</u>	lease created to update Auto High Beam feature to add High Beam sensitivity change logic.	
<u>15073VC</u>	429	<u>97314S</u>	Release created to update the broadcasted country code from Motorola to Intel	
<u>15180VC</u>	429	<u>97314S</u>	Release created to open Lift Axle Control feature for 0597165 IP	
<u>15079VC</u>	429	<u>97314S</u>	744 OP Update	
<u>15155VC</u>	429	<u>97314S</u>	Release created to have only Left side turn signal assist as an available option	
<u>15161VC</u>	429	<u>97314S</u>	Release to override default PP values when 85dB(A) is ordered.	
15286VC	429	<u>97314S</u>	Trailer Detection and calibration rework to allow multiple features to request trailer	
<u>15260VC</u>			detection	
<u>15177VC</u>	429	<u>97314S</u>	Release created to Remove Current_Region_Observe_Time	
<u>15397VC</u>	429	<u>97314S</u>	Release created to update default parameter values and ranges for HSA software.	

Database 428 (Release Date: 6/12/2024)

DLBFR 2024 R1P1P1	428		DLB FR Release for 2024 R1P1P1
<u>15788VC</u>	428	DLBFR 2024 R1P1P1	To open Brake feature for EV

Database 427 (Release Date: 6/12/2024)

<u>97314L</u>	427		2024 R1 Parent Release	
<u>13072VC</u>	427	<u>97314L</u>	Added the HV IP for HX520 Headlamp Support	
<u>13065VC</u>	427	<u>97314L</u>	Release created for Integrated Pre-Trip Inspection	
<u>15045VC</u>	427	<u>97314L</u>	To create new override feature that will disable PTO request from steering wheel cruise switches.	

Database 426 (Release Date: 6/12/2024)

<u>97314H</u>

• Database 425 (Release Date: 4/16/2024)

<u>97314K</u>	425		Parent Release R0p01 2024
15006VC	425	<u>97314K</u>	Production variant of Hill Start Aid WIP
<u>15078VC</u>	425	<u>97314K</u>	743 OP Update
<u>15138VC</u>	425	<u>97314K</u>	631 OP Update
<u>15180VC</u>	425	<u>97314K</u>	Release created to open Lift Axle Control feature for 0597165 IP

• Database 424 (Release Date: 4/16/2024)

<u>972</u>	<u>74S</u>	424		Parent release R4 2023
1314	49VC	424	<u>97274S</u>	To create new feature for Lane Centering
		424	<u>97274S</u>	To create new feature for Auto high beam with warning lights and Updated 0597692 with
138	<u>53VC</u>			new code for Low Beam warning light.

<u>14052VC</u>	424	<u>97274S</u>	Release to be created for Air Governor Control features for addressing DLs.		
<u>14053VC</u>	424	<u>97274S</u>	BCM ePTO Updates		
<u>14114VC</u>	424	<u>97274S</u>	To update Grid Management PP		
	424	<u>97274S</u>	Created release for trailer detection feature codes(5 legs for 1 main trailer detection		
<u>14190VC</u>			feature code)		
<u>14561VC</u>	424	<u>97274S</u>	Legacy Fifth Wheel Jaw Modified to remove the Trailer ABS Status Signal		
	424	<u>97274S</u>	Release created to modify the vehicle speed parameter values for hazard operation during		
<u>14562VC</u>			emergency braking events and Collision events.		
<u>14664VC</u>	424	<u>97274S</u>	Created new parameter values for fan setting and A/C pressure setting		
<u>14742VC</u>	424	<u>97274S</u>	Created release to update HOD Warning Levels		
	424	<u>97274S</u>	To remove steering gear (0x13) and receive msg's from LDW(0xE8) to support ADAS HMI		
<u>14766VC</u>			functionality.		
<u>15061VC</u>	424	<u>97274S</u>	742 OP Update		
<u>15062VC</u>	424	<u>97274S</u>	Release for 630 OP		
<u>15084VC</u>	424	<u>97274S</u>	E89 - PP values update for Wave File Selection & Wave File Play for radio		

• Database 423 (Release Date: 4/16/2024)

<u>15052VC</u>	423		Parent Release for BCM_R0_2024_EXT	
<u>14046VC</u>	423	<u>15052VC</u>	To create new feature for Noise Suppression Switch Horizon	
<u>14291VC</u>	423	<u>15052VC</u>	To create new feature for booster pump with fuel fired heater	
14820VC	423	<u>15052VC</u>	H08 - HVAC Sensor implementation	
<u>15180VC</u>	423	<u>15052VC</u>	Release created to open Lift Axle Control feature for 0597165 IP	
15052VC	423	<u>15052VC</u>	OP 741	

• Database 422 (Release Date: 4/16/2024)

	<u>97314z</u>	422		Parent Release R0p04 2024				
Ī		422	<u>97314z</u>	Fix for removing self arming behavior for 0597646 Post Trip				
	15377VC			Inspection				

• Database 421 (Release Date: 3/25/2024)

<u>97314Y</u>	421		Parent Release R0p4 2024
<u>15320VC</u>	421	<u>97314V</u>	Bus Post Trip Inspection 597features modifications

Diamond Logic Builder Update to 15887 (Release Date: 2/27/2024)

• Licensing restored.

• Database 420 (Release Date: 3/4/2024)

<u>97314V</u>	420		Parent Release R0p03 2024
<u>15186VC</u>	420	<u>97314V</u>	Created to open the Noise Suppression SW feature for EC Bus with integrated heat only
<u>15205VC</u>	420	<u>97314V</u>	To add and update Drive Modes for GW transmission

<u>15281VC</u> 420 <u>97314V</u> To open feature for LT

• Database 419 (Release Date: 2/22/2024)

DLBFR1	419		
<u>15237VC</u>	419	DLBFR1	Update Dome Light active time in Key off

Diamond Logic Builder Update to 15886 (Release Date: 2/19/2024)

- Updates toward restoring Licensing
- Database, Version 418 (Release Date: 2/19/2024)

<u>97314R</u>	418		BCM Parent Release R0p2 2023
			Release created to update
14558VC	418	97314R	Engine_Ramp_with_AC_ON_Hzn codeblock
14744VC	418	97314R	PWL reorder of priority for PWL Cancel Switch
15147VC	418	<u>97314R</u>	Air Door slamming door issue resolved
15169VC	418	97314R	To open feature for E79

• Database, Version 417 (Release Date: 1/23/2024)

DLBFR 01 2024	417		H08 Filter Release No Software modified
15107VC	417	DLBFR_01_2024	H08 Filter Release No Software modified

Diamond Logic Builder Update to 15878 (Release Date 12/21/2023)

• Temporarily removing licensing to allow users to log in.

• Database, Version 416 (Release Date: 12/20/2023)

Release	Data Version	Parent	Description
<u>97314G</u>	416		release for R3p12 2023
<u>14979VC</u>	416	<u>97314G</u>	New feature code to activate dome / courtesy lights when Key is off and External Knob is transitioned
<u>14988VC</u>	416	<u>97314G</u>	Release to create feature similar to 0597271 without Park Position Unlock Solenoid

• Database, Version 415 (Release Date: 12/20/2023)

D - I -

Release	Data Version	Parent	Description
<u>97174U</u>	415		BCM_R3p2_2023_EXT
<u>13150VC</u>	415	<u>97174U</u>	Release created for Blind Spot Detection
<u>14040VC</u>	415	<u>97174U</u>	Created release for H06 Wheelchair Interlock
<u>14120VC</u>	415	<u>97174U</u>	701 Fifth Wheel Jaw Unlock Trailer

			Connected Cluster Pop-Up
<u>14483VC</u>	415	<u>97174U</u>	Update filter rules to add compatibility for E44 and remove 0597173
<u>14643VC</u>	415	<u>97174U</u>	Updated to add ePTO pseudo teach for EV
<u>14862VC</u>	415	<u>97174U</u>	740 OP Update

Diamond Logic Builder Update to 15875 (Release Date 11/07/2023)

- DLB-319 EV Cluster ePTO H01 support
- DLB-248 CAN Transmission Shift Actuator (detection only)
- Database, Version 414 (Release Date: 12/04/2023)

Release	Data Version	Parent	Description
<u>97314F</u>	414		R3_2023 (Horizon Cluster 040457 and 040336)

• Database, Version 413 (Release Date: 11/09/2023)

Release	Data Version	Parent	Description
DLBFR R3p11 2023	413		DLB C-Rule Update for feature code 597541 Inclusion Rule
<u>14960VC</u>	413	DLBFR_R3p11_2023	701 filter rule update for 13WEX

Diamond Logic Builder Update to 15859 (Release Date 6/27/2023)

- Fix to Trailer Cord Detection function.
- Database, Version 412 (Release Date: 11/07/2023)

Release	Data Version	Parent	Description
<u>97174J_2</u>	412		05.09.02 EV Cluster

Diamond Logic Builder Update to 15859 (Release Date 6/27/2023)

- Fix to Trailer Cord Detection function.
- Cluster programming fix

• Database, Version 411 (Release Date: 11/05/2023)

Release	Data Version	Parent	Description
<u>97174T</u>	411		BCM_R3p1_2023_EXT 97174T
<u>12975VC</u>	411	97174T	Release created for Engage Trailer Service Brakes feature
<u>13148VC</u>	411	97174T	Release created for Active Steering
<u>14041VC</u>	411	97174T	To Create AIR COMPRESSOR MOTOR INHIBIT for High Voltage system for Horizon EV Bus.
<u>14186VC</u>	411	97174T	Created release to add CAL-CON for Audible 4- Way Hazard Tick Tock
<u>14214VC</u>	411	97174T	Release created for E82 Transfer Case Temp Gauge.

14491\/C	411	97174T	E44 Transmission PTO Features with 42
<u>14481VC</u>			Parameters
<u>14482VC</u>	411	97174T	Release for updating TEM bucket with PTO
			signals for controlling Scania Transmission
<u>14662VC</u>	411	97174T	To open 0597069, 0597705, 0597714 for H06
			Platform
<u>14770VC</u>	411	97174T	Release for supporting 739 OP Update

• Database, Version 410 (Release Date: 10/29/2023)

Release	Data Version	Parent	Description
<u>97274A</u>	410		BCM_R3p05_2023_EXT
<u>14786VC</u>		<u>97274A</u>	Release to reorder the MUX for CE Bus 2.0 Solenoids

• Database, Version 409 (Release Date: 09/21/2023)

Release	Data Version	Parent	Description
<u>97174J</u>	409		EV Cluster ePTO 090501

• Database, Version 408 (Release Date: 09/21/2023)

Release	Data Version	Parent	Description
<u>97174H</u>	408		Horizon Cluster Software R2p3_2023 and R2p4_2023

• Database, Version 407 (Release Date: 09/7/2023)

Release	Data Version	Parent	Description
<u>97125L</u>	407		2023 R3 Parent Release
<u>13429VC</u>		<u>97125L</u>	Created release to have Engine Guard for X15
<u>14319VC</u>		<u>97125L</u>	Release Created for Air Governor Features updates on addressing DLs and updated ESI requirements.
<u>14495VC</u>		<u>97125L</u>	Door pop-ups; Door overcurrent Attempt limit

• Database, Version 407 (Release Date: 09/7/2023)

Release	Data Version	Parent	Description
<u>97125L</u>	407		2023 R3 Parent Release
<u>13429VC</u>		<u>97125L</u>	Created release to have Engine Guard for X15
<u>14319VC</u>		<u>97125L</u>	Release Created for Air Governor Features updates on addressing DLs and updated ESI requirements.
<u>14495VC</u>		<u>97125L</u>	Door pop-ups; Door overcurrent Attempt limit
<u>14508VC</u>		<u>97125L</u>	PTO feature updated by Adding PTO Hours teach information,

<u>14651VC</u>	<u>97125L</u>	Release for 738 OP Update
<u>14746VC</u>	<u>97125L</u>	To update user usage in Bus_PWL_Overide_Signal_Filter codeblock.

• Database, Version 406 (Release Date: 09/1/2023)

Release	Data Version	Parent	Description
<u>97174F</u>	406		EV Cluster Kernel to 90500
Database, Version 405 (Release Date: 07/27/2023)			2023)
Release	Data Version	Parent	Description
97051M	405		FY 2023 BC Software R2.1

<u></u>			
<u>13520VC</u>	405	<u>97051M</u>	Release created for E99 Downhill Speed Control functionality
<u>14050VC</u>	405	<u>97051M</u>	Created release to open 0597697 for eLT
<u>14101VC</u>	405	<u>97051M</u>	release created to fix intermittent activation of red override signal in key crank.

• Database, Version 404 (Release Date: 07/24/2023)

Release	Data Version	Parent	Description
<u>97174E</u>	404		FY 2023 BC Software R2.1
<u>14435VC</u>	404	<u>97174E</u>	Release for creating EV version of GW Transmission PTO

• Database, Version 403 (Release Date: 07/24/2023)

Release	Data Version	Parent	Description
<u>97125J</u>	403		R2p1_2023 cluster base 040333 and R2p2_2023 cluster premium 040454

• Database, Version 402 (Release Date: 07/14/2023)

Release	Data Version	Parent	Description
<u>97073B</u>	402		2023 R1p3 Parent Release
<u>13775VC</u>	402	<u>97073B</u>	Door release with wakeup input as Fwd latch DIN (without wiring changes).
<u>13777VC</u>	402	<u>97073B</u>	Created to add Dome lights functionality to 47KEB PTI
<u>13991VC</u>	402	<u>97073B</u>	To create New Features for Dome light activation
<u>14109VC</u>	402	<u>97073B</u>	Release created to update Door Ajar Popup and Alarm Suppress when Noise Suppression Switch is ON
<u>14128VC</u>	402	<u>97073B</u>	Release to be created for PWL Mux Indicator.
<u>14130VC</u>	402	<u>97073B</u>	Release created to open DLB for M-CE bus
<u>14177VC</u>	402	<u>97073B</u>	To create new feature for wheelchair lift Indicator

<u>14178VC</u>	402	<u>97073B</u>	Phase 2 External knob added
<u>14229VC</u>	402	<u>97073B</u>	Release to update the user usage of BUS_Wheelchair_Lift_Door_Switch in feature 597647
<u>14371VC</u>	402	<u>97073B</u>	Release created to have addon feature for Post Trip Inspection Snooze Switch
<u>14381VC</u>	402	<u>97073B</u>	Release to be created for Emergency Exit features with/ without audible alarm.
<u>14580VC</u>	402	<u>97073B</u>	Release to open 0597624 for E79

• Database, Version 401 (Release Date: 07/14/2023)

Release	Data Version	Parent	Description
<u>97073A</u>	401		2023 R1p3 Parent Release
<u>13043VC</u>	401	<u>97073A</u>	Door release with wakeup input as Fwd latch DIN (without wiring changes).
<u>13235VC</u>	401	<u>97073A</u>	Created to add Dome lights functionality to 47KEB PTI
<u>13881VC</u>	401	<u>97073A</u>	To create New Features for Dome light activation
<u>14015VC</u>	401	<u>97073A</u>	Release created to update Door Ajar Popup and Alarm Suppress when Noise Suppression Switch is ON
<u>14115VC</u>	401	<u>97073A</u>	Release to be created for PWL Mux Indicator.
<u>14436VC</u>	401	<u>97073A</u>	Release created to open DLB for M-CE bus
<u>14437VC</u>	401	<u>97073A</u>	To create new feature for wheelchair lift Indicator

• Database, Version 400 (Release Date: 06/16/2023)

Release	Data Version	Parent	Description
<u>96991B</u>	400		2023 R1.1 Parent Release
<u>11409VC</u>	400	<u>96991B</u>	Release to update Grid Control for OTA Programming for BCM OTA
<u>12655VC</u>	400	<u>96991B</u>	Release Created to add Engine Guard Teach Configuration for Cummins Diesel Engine.
<u>12954VC</u>	400	<u>96991B</u>	Release created to update Crank Inhibit feature with Stalk shift to Inhibit cranking when stalk shifter position is not in N or P.
<u>12973VC</u>	400	<u>96991B</u>	Updated code block to transmit ASCII value of Country Code to Camera as data received from

			PCC or EGC
<u>14042VC</u>	400	<u>96991B</u>	Release created to update Pin mapping for 597600 from DIN09 to DIN19
<u>14065VC</u>	400	<u>96991B</u>	Created release to open 597529 (TPMS) feature for CE Bus platform.
<u>14131VC</u>	400	<u>96991B</u>	Release for updating 736, 628, and 514 OP's
<u>14167VC</u>	400	<u>96991B</u>	Release to create new 506 Controllers and Features

Diamond Logic Builder Update to 15855 (Release Date 4/28/2023)

- Enhanced Trailer Cord Detection Function.
- Show version information in Windows properties.
- EV module descriptions have been updated, but SA 90 (VCM) is still showing as "Unknown module."

• Database, Version 399 (Release Date: 04/14/2023)

Release	Data Version	Parent	Description
<u>97017H</u>	399	<u>96827W</u>	Clusters Update Base 4.03.31 Premium 4.04.51

Diamond Logic Builder Update to 15849 (Release Date 4/13/2023)

• Electric vehicle cluster updates.

Diamond Logic Builder Update to 15843 (Release Date 2/19/2023)

- Premium cluster and electric vehicle cluster updates.
- Database, Version 398 (Release Date: 03/08/2023)

Release	Data Version	Parent	Description
<u>96827W</u>	398		2023 R1 Parent Release
<u>12531VC</u>	398	<u>96827W</u>	To activate Hazard lights during CMS event
<u>13223VC</u>	398	<u>96827W</u>	To create new features that will eliminate extra coding words for gauges in cluster.
<u>13377VC</u>	398	<u>96827W</u>	Release to be created for Perimeter Lighting
<u>13380VC</u>	398	<u>96827W</u>	Release created to update Bus Door Opening & Dome light Activation in Key OFF
<u>13462VC</u>	398	<u>96827W</u>	Release created to override a value to 248F for Global Export Trucks(EXP).
<u>13548VC</u>	398	<u>96827W</u>	Release created to update air doors to turn OFF the BCM Close Command pin when the door is fully closed
<u>13715VC</u>	398	<u>96827W</u>	Update GridCtrl_Abutment_ON_Time for Cummins L9 Engine
<u>13734VC</u>	398	<u>96827W</u>	To Open feature code 0597571 for 0597164
<u>13864VC</u>	398	<u>96827W</u>	Release created to update output pin for underhood_light_cmd for CE Bus 2.0

• Database, Version 397 (Release Date: 02/19/2023)

Release	Data Version	Parent	Description
DLBFR ROP3 2023	397		DLBFR Release for 597711 rule
<u>14116VC</u>	397	DLBFR_R0P3_2023	Release to open 0597711 for eMV and eLT

Diamond Logic Builder Update to 15841 (Release Date 12/15/2022)

• Resolved issue with electric vehicle HVAC module updates.

Database, Version 396 (Release Date: 02/17/2023)

Release	Data Version	Parent	Description
<u>96827T</u>	396	<u>96991A</u>	EV Cluster 5.03.00

Database, Version 395 (Release Date: 02/13/2023)

Release	Data Version	Parent	Description
<u>96991A</u>	395		R0p1 2023 Parent Release
<u>14001VC</u>	395	<u>96991A</u>	Release to update Constant Value's for Brake Pressed and Released

Database, Version 394 (Release Date: 02/08/2023)

Release	Data Version	Parent	Description
DLBFR 02 23	394		DLBFR Release Feb 2023
<u>14068VC</u>	394	DLBFR_02_23	Open features for H08, CE Bus
<u>14097VC</u>	394	DLBFR 02 23	Change signal permissions needed for Trailer Cord Detection Calibration

Database, Version 393 (Release Date: 02/02/2023)

Release	Data Version	Parent	Description
<u>96827V</u>	393		BCM R4_2022
<u>12496VC</u>	393	<u>96827V</u>	Trailer Cord Detection: Accessor function for Low Current values
<u>13147VC</u>	393	<u>96827V</u>	Release for adding OTAPM Door Unlock/Lock functionality
<u>13569VC</u>	393	<u>96827V</u>	Release to update naming scheme for GW/T14 Transmission Mode
<u>13880VC</u>	393	<u>96827V</u>	OP735 Update

Database, Version 392 (Release Date: 12/20/2022)

Release	Data Version	Parent	Description
<u>96700J</u>	392		BCM R3_2022

11273VC	392	96700J	update SW of Suspension Primaax
12026VC	392	<u>96700J</u>	Release created for a new diff lock feature code with Parameter Max_Diff_Lock_Speed_Special_Case
<u>12424VC</u>	392	<u>96700J</u>	Release to add Pass Assist functionality for Adaptive Cruise Control
<u>12498VC</u>	392	<u>96700J</u>	Release for Intellipark Trailer Detection
<u>12632VC</u>	392	<u>96700J</u>	Release to create a feature for Heated Headlamps
<u>12633VC</u>	392	<u>96700J</u>	Release to add Fusion 3 Features to Horizon CE Bus
<u>12810VC</u>	392	<u>96700J</u>	To create Intellipark Brake Feature for Bus
<u>12811VC</u>	392	<u>96700J</u>	Open Park Brake Relay 0597274 for E79
12950VC	392	<u>96700J</u>	Release created to update bus electric door feature to support new CAN based logic
<u>12953VC</u>	392	<u>96700J</u>	Release to create new feature for overriding Auto S/S Idle Speed (cummins engine).
<u>13007VC</u>	392	<u>96700J</u>	Release created to open Logic Builder Feature to eMV IP
<u>13075VC</u>	392	<u>96700J</u>	Release to support E71 changes.
<u>13151VC</u>	392	<u>96700J</u>	Created Engine_Fan_Override_Hzn codeblock for Horizon and added code reference in 0597037 feature.
13158VC	392	<u>96700J</u>	Release created to update code block of heated mirrors
<u>13195VC</u>	392	<u>96700J</u>	To update code of Rock Free Transmission mode 11 active for falling Edge
<u>13244VC</u>	392	<u>96700J</u>	To update Pin mapping of Strobe Light Switch Input from AIN23 to AIN08
<u>13378VC</u>	392	<u>96700J</u>	 PTI feature modifications for following changes: 1. ESI 2014-08: New feature creation. 2. ESI 2014-05: 0597645, add self-arm timer. 3. ESI 2014-07: 0597647, to add door lift signal as interlock while disarming 4. To add 1 short beep after disarm switch is pressed 5. To add optional Mux indicator
<u>13466VC</u>	392	<u>96700J</u>	Release for 734 OP Update
<u>13570VC</u>	392	<u>96700J</u>	Release to update how Send On Change for Brake Application Air Command (SPN 116) Only is implemented.

Database, Version 391 (Release Date: 12/15/2022)

Release	Data Version	Parent	Description	
<u>96915K</u>	391		H08 R3.1 2022 Hyperion SW	
<u>12033VC</u>	391	<u>96915K</u>	Release created for new IP feature for eTractor	
<u>12079VC</u>	391	<u>96915K</u>	Release created to update C-Rule for 0597083 to include e-Tractor IP Feature	

<u>12374VC</u>	391	<u>96915K</u>	Release created to open LT/RH features to eTractor IP
<u>12375VC</u>	391	<u>96915K</u>	Release created to open eMV features to eTractor
<u>12376VC</u>	391	<u>96915K</u>	Created release to open LT/RH features to eTRACTOR.
<u>12377VC</u>	391	<u>96915K</u>	Release created to open eMV features to eTractor
<u>12533VC</u>	391	<u>96915K</u>	Release created to open 0597640 for eTractor
<u>13246VC</u>	391	<u>96915K</u>	To open LT/RH features(dependent on Teach) for eLT platform for H08 program.

Diamond Logic Builder Update to 15840 (Release Date 11/10/2022)

• Added Support for TPMS Gen 2.

Database, Version 390 (Release Date: 12/10/2022)

Release	Data Version	Parent	Description
DLBFR12 22	390		E44 DLB Filter Rule
<u>13874VC</u>	390	DLBFR12_22	Open up 0597483 to IP 0597003 and 0597165

Database, Version 389 (Release Date: 11/14/2022)

Release	Data Version	Parent	Description
<u>96827G</u>	389		Cluster kernel updates. Premium 04.04.49, Base 04.03.29

Diamond Logic Builder Update to 15829 (Release Date 10/31/2022)

• Update for common messaging with Single Sign On.

Database, Version 388 (Release Date: 10/20/2022)

Release	Data Version	Parent	Description	
<u>96827D</u>	388		2022 R2p2 Parent Release	
<u>13465VC</u>	388	<u>96827D</u>	Release created to update Pin mapping of Crossing Gate Command Output and update to change multiplexer output.	

Diamond Logic Builder Update to 15818 (Release Date 10/14/2022)

• Update to add Single Sign On (SSO) support.

Diamond Logic Builder Update to 15817 (Release Date 06/27/2022)

• Update to resolve connection issues to trucks with new clusters.

Database, Version 387 (Release Date: 08/25/2022)

Release	Data Version	Parent		Description
---------	-----------------	--------	--	-------------

<u>96700F</u>	387		Release 96700F (FY 2022 BC Software R2.1)
<u>13370VC</u>	387	<u>96700F</u>	Noise Suppression feature for eBUS 1.5
<u>13428VC</u>	387	96700F	Release for 627 OP

Database, Version 386 (Release Date: 08/12/2022)

Release	Data Version	Parent	Description
Cluster Updates	386		Base Cluster 04.03.28 and Premium 4.44.47

Database, Version 385 (Release Date: 08/03/2022)

Release	Data Version	Parent	Description
ClusterRollback	385		Horizon premium cluster roll back to 04.04.40

Database, Version 384 (Release Date: 07/26/2022)

Release	Data Version	Parent	Description
<u>96671W</u>	384		Horizon premium cluster 04.04.46

Database, Version 383 (Release Date: 07/21/2022)

Release	Data Version	Parent	Description
DLBFR R2p22022	383		DLB Filter release to allow 0597677 to configure with 0597003 LT IP
072022DLBFR	383	DLBFR_R2p22022	Filter Release for updating 0597677 C-Rule

Database, Version 382 (Release Date: 07/15/2022)

Release	Data Version	Parent	Description
DLBFR R2p12022	382		DLB Filter release to allow 0597676 to configure with 0597003 LT IP
071522DLBFR	382	DLBFR_R2p12022	Release for adding LT IP for 0597676 Suspension dump

Database, Version 381 (Release Date: 06/24/2022)

Release	Data Version	Parent	Description
<u>96531T</u>	381		2022 R2 Parent Release
<u>12352VC</u>	381	96531T	To create new DEF tank capacity features.
<u>12411VC</u>	381	96531T	Release created to transmit Secure Brake Switch and Cruise Enable Signal to PIM and to update Prop SPN for Brake & cruise Msg for ECM Module
<u>12489VC</u>	381	96531T	Created Release to add Faults for Loss Comm between BCM and Left/ Right Headlamps
<u>12497VC</u>	381	96531T	Release created to change Fault filtering of

			Park/Marker output
<u>12599VC</u>	381	96531T	Release to open features for eBus IP
<u>12638VC</u>	381	96531T	Update Headlights functionality to address DL- 6617
<u>13010VC</u>	381	96531T	Release Created to Update AIN definition Ranges
<u>13044VC</u>	381	96531T	Added SPN 3940 in PGN 64932 to fix Pyxis 599355
<u>13054VC</u>	381	96531T	Release for OP 733 Update
<u>9356VCM</u>	381	96531T	Created Release for new SSPTO Features for Horizon

Database, Version 380 (Release Date: 06/14/2022)

Release	Data Version	Parent	Description
<u>96531U</u>	380		2022 R1.2 Parent Release
<u>13026VC</u>	380	96531U	Update temperature parameter thresholds to fix Pyxis 602331.
<u>13033VC</u>	380	96531U	Release for updating TEM PTO and Transmission PTO features
<u>13144VC</u>	380	96531U	Update the access level for Cabin Heater Low Threshold parameter

Diamond Logic Builder Update to 15814 (Release Date 06/09/2022)

• Update to resolve database issues.

Database, Version 379 (Release Date: 06/09/2022)

Release	Data Version	Parent	Description
<u>96531N</u>	379		FY BCM_R1p1_2022_EXT
<u>12988VC</u>	379	96531N	Release for 732 OP
<u>13016VC</u>	379	96531N	0597623 inclusion C-Rule to update
<u>13017VC</u>	379	96531N	Added Solenoid_Over_Current_Status in 0595JAS & transmission constants in 0595BZS features.

Diamond Logic Builder Update to 15812 (Release Date 04/12/2022)

• Update to Electric Vehicle Instrument Cluster Kernel

Database, Version 378 (Release Date: 3/08/2022)

Release	Data Version	Parent	Description
96442Y	378		FY 2022 R1 Parent Release

11337VC	378	96442Y	Release Created to support Electronic Air Governor
			Control functionality.
12016VC	378	96442Y	Release created to transmit FEPTO/REPTO status
			message to TCM\ECM
12022VC	378	96442Y	Created release for T-Case Temp Warning
			functionality
12118VC	378	96442Y	C-Rule update for Drive Mode features
12121VC	378	96442Y	Release created to update sleeper functionality for digital input.
12191VC	378	96442Y	Release to update message processing of SPN 3463
12199VC	378	96442Y	Release created for N2 Load Shed Improvement
12222VC	378	96442Y	Created release to fix feature per EES-SE-I-5097-01
			ver 1.1
12225VC	378	96442Y	Release for Remote Start Stop Update to reset
			Failed Attempt Flag when Engine is running and
			remove
12243VC	378	96442Y	Release created to update Park Brake Alarm Feature
12513VC	378	96442Y	Release created to update access level of signals as
			per guidelines
12532VC	378	96442Y	Release for updating 731 OP
12600VC	378	96442Y	Release Created for Pin Update for Parked Regen
			Switch
12600VC	378	96442Y	Release created to change active filtering time in
			NM-Safety-Direct-Processor-Module
12898VC	378	96442Y	To resolve the hyperion conflicting issue for 595KBH
			and 595BJR.

Database, Version 377 (Release Date: 2/16/2022)

<u>96531G</u>	377		FY 2022 R0.1 Parent Release
<u>12820VC</u>	377	<u>96531G</u>	Release created to fix Pyxis 593726 (ABS Indicator Lamp Inversion issue)
	377		Fix for Park Brake Alarm with key ON issue

Database, Version 376 (Release Date: 12/22/2021)

<u>96400Z</u>	376		2021 R4 Parent Release
<u>10082VC</u>	376	96400Z	Created new release for fixing timing issue in Load shed horizon code block
<u>10489VC</u>	376	96400Z	Release created to updated Lift Axle Module
<u>11080VC</u>	376	96400Z	Release created to add Mux PA in Radio functionality
<u>11423VC</u>	376	96400Z	Created release to update existing Auxiliary Transmission feature to send status of Low/High/Neutral Gear Over CAN

<u>11085VC</u>	376	96400Z	Updates for Lift Axle with ELAM. PP config units
			resolution is too low and resulting in incorrect Pressure Resolution value
<u>11525VC</u>	376	96400Z	Created release to support Turn Signal Lights command in PGN 65089
<u>11582VC</u>	376	96400Z	Release created to correct the SPN for Right_Headlamp_RX_Message_Counter in NM-Horizon- Right-Headlamp module.
<u>11661VC</u>	376	96400Z	Release created to add auto Relay fault code definition.
<u>11690VC</u>	376	96400Z	Release to create new feature for Stationary
			Regeneration when time since Active regen is greater than the time defined in the Programmable Parameter.
<u>11673VC</u>	376	96400Z	Release created to update LDW feature for Camera Event Recorder logic.
<u>11833VC</u>	376	96400Z	Update Starter Activation Time from 2 seconds to 4 seconds
<u>11855VC</u>	376	96400Z	Update for Loss of Comms Fault Logging in Key Off
<u>12047VC</u>	376	96400Z	Release to create two new optional feature codes for Dome Lights Activation through Doors and Emergency Exit.
<u>11997VC</u>	376	96400Z	Release created for H04 Simplified Cluster Teach
<u>12140VC</u>	376	96400Z	OP Task for updating 730
<u>12242VC</u>	376	96400Z	626 OP Update
<u>12256VC</u>	376	96400Z	Disable AEBS2 from 250K BB datalink
12389VC	376	96400Z	Release created to remap E79 DIN conflict
<u>8743VCM</u>	376	96400Z	Release created to update Fog Lights Horizon feature
<u>9115VCM</u>	376	96400Z	Created release to have a feature code similar to 0595ALG
<u>9118VCM</u>	376	96400Z	Release created for Fog Lights feature for CE Bus 2.0
<u>9326VCM</u>	376	96400Z	To support Air Suspension Dump functionality for Monostable switch.

Database, Version 375 (Release Date: 12/01/2021)

<u>96442N</u>	375		2021 R3.3 Parent Release
<u>12519VC</u>	375	96442N	Release to update No Idle heater without condensation blower to reverse the active low relay object to active high

Database, Version 374 (Release Date: 11/20/2021)

<u>96400G</u> 374	base 04.03.24, premium 04.04.40, EV 04.02.00
-------------------	--

Database, Version 373 (Release Date: 11/15/2021)

<u>96370D</u>	373	E79 D5 Parent Release	

1011010	070	0.00700	
<u>10110VC</u>	373	96370D	Release created for new Noise Suppression feature for CE Bus 2.0
<u>10127VC</u>	373	96370D	Release created for E79 Bus Stop Arm feature.
<u>10146VC</u>	373	96370D	Create a new feature for Alternating Flashing Lighting (Wig Wag) with Bus Pupil Warning Lights
<u>10148VC</u>	373	96370D	Created release for CE Bus Headlights
<u>10289VC</u>	373	96370D	E79 D5 IP Update for Adding and Removing Features
<u>10382VC</u>	373	96370D	Created release to Brake Switch feature for CE Bus Horizon
<u>10732VC</u>	373	96370D	Release to create new Dome Light features
<u>10965VC</u>	373	96370D	Created release to open Auto High Beam feature for CE BUS Horizon platform
<u>10982VC</u>	373	96370D	Release created for Beacon/Strobe Light Features.
<u>11156VC</u>	373	96370D	Created release for Steering Wheel Switch Pod for E79 platform
<u>9094VCM</u>	373	96370D	Release created for new ELC feature for E79 Bus.
<u>9095VCM</u>	373	96370D	Release to create new feature for Crossing Gate Disable Switch
<u>9104VCM</u>	373	96370D	Release to create sequential PWL Steering Wheel features for Horizon CE Bus.
<u>9105VCM</u>	373	96370D	Release to create the common outputs PWL feature, Non-Sequential PWL Steering Wheel features, Red Always Hot PWL feature and PWL Master Cancel features for Horizon CE Bus.
<u>9107VCM</u>	373	96370D	Created release for Pupil Warning Lights (Sequential) Options
<u>9108VCM</u>	373	96370D	Created release for Pupil Warning Lights (Non- Sequential) Options
<u>9119VCM</u>	373	96370D	To create new feature for Auxiliary Air Pressure Gauge for Bus without Door Switch.
<u>9129VCM</u>	373	96370D	To create a new Post Trip Inspection feature for horizon
<u>9130VCM</u>	373	96370D	Release to create new feature for PTI Child Reminder System
<u>9133VCM</u>	373	96370D	Release created for new Headlight Reminder Feature
<u>9151VCM</u>	373	96370D	Release created for Park Brake Alarm features for Horizon Bus
<u>9158VCM</u>	373	96370D	To create new feature for Interlock wheelchair functionality with Warning Lamp.

Database, Version 372 (Release Date: 11/02/2021)

<u>96400Y</u>	372		BCM_R3p2_2021_ExT
<u>12244VCM</u>	372	96400Y	Update ITAR Global Network module to keep in sync with

Diamond Logic Builder Update to 15800 (Release Date 09/22/2021)

• GUI & Emitter changes for Comm. Loss in Key OFF.

<u>96253K</u>	371		2021 R3 Parent Release
<u>10259VC</u>	371	96253K	Release created for Intellipark Feature CA2.0
<u>10260VC</u>	371	96253K	Release created for Intellipark Feature CA1.5 and
			moved SPN 1820 from Data Recorder feature to all
101171/0	271	002521/	Wheelchair Interlock features.
<u>10447VC</u>	371	96253K	Release Created to Change the ABS Warning Relay from Active low to Active High
10869VC	371	96253K	Release created for ACC following mode selection
			Release created for Transmission Mode Selection
<u>10979VC</u>	371	96253K	feature for new Eaton Transmission.
<u>10980VC</u>	371	96253K	Release Created for XD/XDPRO Eaton Transmission
11082VC	371	96253K	Release created to support Steering Wheel
			Controls feature
<u>11083VC</u>	371	96253K	Created release for Perimeter Lighting
			Update Load Shed Features to stop and prevent
<u>11188VC</u>	371	96253K	shedding if OTAPM is programming. Remove Battery Interlock trip for pre-condition and active-
			programming condition.
112251/0	271	062524	Release Created for Neutral at Stop feature to
<u>11325VC</u>	371	96253K	support ACC stop and auto go functionality
11479VC	371	96253K	Release to create new feature for Blind Spot
			Radar.
11535VC	371	96253K	Release created to add generic NAVISTAR
44520140		0.00501/	Messages in Radio Mute Feature
<u>11539VC</u>	371	96253K	Release created for NFC Fuel Tank Capacity
<u>11548VC</u>	371	96253K	To enable PGN 61441 for 250K Private bus in 6xx
<u>11781VC</u>	371	96253K	Regen Braking Changes for eMV H07
<u>11782VC</u>	371	96253K	Release created to update interlock for Auto High Beams Horizon
<u>11792VC</u>	371	96253K	Release to create 729 OP
<u>11969VC</u>	371	96253K	Release to create 625 OP
<u>12032VC</u>	371	96253K	Release to open 0595AGP for EV Bus IP.
12049VC	371	96253K	To remove CAL-CONs related to Front/Rear Axle
			Location as Cluster does not support them.
<u>12050VC</u>	371	96253K	Release to update Drive Mode with switch Teach Data.
<u>12143VC</u>	371	96253K	Release created for Cluster Teach for Cabin Heater
<u>9354VCM</u>	371	96253K	Initial creation for Force Hold Neutral.
<u>9355VCM</u>	371	96253K	Release created for Rock Free Transmission.
<u>9485VCM</u>	371	96253K	To create new feature for radio fusion

Diamond Logic Builder Update to 15792 (Release Date 09/20/2021)

- Provide electric vehicle cluster programming for Engineering.
- Enhancement for eFIX management

Database, Version 370 (Release Date: 9/02/2021)

DLBFR21	370		Diamond Logic Builder Filter Rule, 21st(DLBFR21) unscheduled release
12088VC	370	DLBFR21	Release to open 0597584 for eMV IP.

Database, Version 369 (Release Date: 8/11/2021)

<u>96214W_2</u>	369	Re-release 1.41 ELAM

Database, Version 368 (Release Date: 8/11/2021)

<u>96318N</u>	368		FY 2021 R2.3 BC Software Release
			Update for ignoring Not Available from ELAM until after
<u>12004VC</u>	368	<u>96318N</u>	switch press or Normal Operation from ELAM

Database, Version 367 (Release Date: 8/05/2021)

<u>12023VC</u>	367	To open 0595AGZ for EV Bus
DLBFR20	367	DLB Filter rule to open 595AGZ for IP feature 595BZN

Database, Version 366 (Release Date: 8/08/2021)

96318M 366 ELAM 1.38

Database, Version 365 (Release Date: 8/05/2021)

<u>96253S</u>	365		2021 R2.2 Parent Release
<u>11780VC</u>	365	<u>96253S</u>	Release for updating Regenerative Braking for EV Bus
<u>11793VC</u>	365	<u>96253S</u>	Release to create 624 OP

Database, Version 364 (Release Date: 8/04/2021)

96	<u>253G</u>	364	Base 04.03.21 Premium 04.04.37

Database, Version 363 (Release Date: 7/29/2021)

<u>302333</u> 303	96253J	363	ELAM 1.41	

Database, Version 362 (Release Date: 7/28/2021)

<u>96253H</u>	362		2021 R2.1 Parent Release
			ELAM Emergency Change to Send Position Messages in Key Off until expiration, which will send Not Available
<u>11838VC</u>	362	<u>96253H</u>	after

Database, Version 361 (Release Date: 7/28/2021)

<u>96081Y</u>	361		E79 D4 Hyperion master release
<u>10149VC</u>	361	<u>96081Y</u>	Release created for CAN based turns in front and separate hardwired stop/turns in rear.
<u>10274VC</u>	361	<u>96081Y</u>	Created release for Emergency Exit feature for CE Bus.

<u>9116VCM</u>	361	<u>96081Y</u>	Release to Create a feature code similar to 0595ALH
<u>9120VCM</u>	361	<u>96081Y</u>	Create new feature similar to 0595AMH and update the codeblock according to new requirements
<u>9127VCM</u>	361	<u>96081Y</u>	Created to remove load shed interlock from existing Transmission Mode Selection feature.
<u>9147VCM</u>	361	<u>96081Y</u>	Release to Create new feature similar to 0595BPJ and update the Codeblock according to new requirements.
<u>9149VCM</u>	361	<u>96081Y</u>	reated release for new Park/Marker Lights ON W/DRL feature for Hzn
<u>9163VCM</u>	361	<u>96081Y</u>	Release to create feature for CE Bus similar to 0595JAJ- Adjustable Pedals
9206VCM	361	<u>96081Y</u>	create new DPF hardwired regen feature for CE Bus.
<u>9670VCM</u>	361	<u>96081Y</u>	Created release to open 0597122,0597121 to Horizon BUS.

Database, Version 360 (Release Date: 7/02/2021)

<u>96224L</u>	360		G62 Parent Release
<u>11844VC</u>	360	<u>96224L</u>	Open 0597169 for Military IP

Database, Version 359 (Release Date: 6/17/2021)

<u>96120V</u>	359		FY 2021 R2 Parent Release
<u>10868VC</u>	359	<u>96120V</u>	Release created to add constant value for One_Tenth_Second_Delay back to feature 0595313.
<u>9673VCM</u>	359	<u>96120V</u>	Add support for GW Transmission and CBE1 Engine parameters 597496 597444
<u>9481VCM</u>	359	<u>96120V</u>	Initial Creation for Adaptive Cruise Control functionality for CE Bus 0595JAT
<u>9268VCM</u>	359	<u>96120V</u>	Release created for Transmission PTO Split Functionality with Mux Switch 597521
<u>7347VCM</u>	359	<u>96120V</u>	New Release to create new feature for Headlights ON with Auto Headlights with Solar Twilight Sensor 0597584
<u>11543VC</u>	359	<u>96120V</u>	728 OP Update
<u>11542VC</u>	359	<u>96120V</u>	623 OP Update
<u>11399VC</u>	359	<u>96120V</u>	Release to fix issue related to BCM waking up periodically due to activated 250k PT bus
<u>11369VC</u>	359	<u>96120V</u>	Created to add Network Modules in 0597156 and 0597157 feature
<u>11333VC</u>	359	<u>96120V</u>	Release to add simplified teach to the EV Cluster
<u>11331VC</u>	359	<u>96120V</u>	Release created to change DLB Plow Light Parameter permissions from Engineering to FLEETS.
<u>10652VC</u>	359	<u>96120V</u>	Release created to remove mismatch diagnostics logic for Left Turn and Right Turn for J1939 output
<u>10487VC</u>	359	<u>96120V</u>	Release created for NFC for RPM Momentary Switches
<u>10314VC</u>	359	<u>96120V</u>	Release created to allow turn signal to override hazard lights.
<u>10285VC</u>	359	<u>96120V</u>	Release created for new GW Hot Shift PTO IP Switch Features. 0597584
<u>10213VC</u>	359	<u>96120V</u>	Release created for Fifth Wheel Jaw Unlock with Lamp Detection

10040VC	359	961201/	New Release to create features for New Transmission Modes
1004070	555	501207	Release created for new GW PTO Features. 597553
<u>10013VC</u>	359	<u>96120V</u>	597554

Diamond Logic Builder Update to 15792 (Release Date 06/15/2021)

• Provide warning dialog before ELAM flashing.

Database, Version 358 (Release Date: 06/14/2021)

<u>96214W</u>	358	Electronic Lift Axle Module 1.38

Database, Version 357 (Release Date: 06/14/2021)

<u>96214U</u>	357		2021 R1.2 Parent Release
<u>11749VC</u>	357	<u>96214U</u>	Emergency Electronic Lift Axle Module release

Database, Version 356 (Release Date: 05/14/2021)

<u>95985D</u>	356		
<u>9666VCM</u>	356	<u>95985D</u>	open 0597043 to Horizon Bus.
<u>9152VCM</u>	356	<u>95985D</u>	new feature for PARK BRAKE Release Interlock for Horizon 597565
<u>9125VCM</u>	356	<u>95985D</u>	create Engine Ramp with Low Battery feature for CE Bus.
<u>9124VCM</u>	356	<u>95985D</u>	new ENGINE RAMP With A/C ON feature for Horizon CE Bus

Diamond Logic Builder Update to 15786 (Release Date 04/12/2021)

- Added improved parsing for Switch Pack and Cluster serial numbers.
- Added enhanced logging during Switch Pack programming.

Database, Version 355 (Release Date: 04/15/2021)

<u>96120U</u>	355		FY 2021 R1.1 Parent Release
<u>11520VC</u>	355	<u>96120U</u>	Add Left/Right Turn Signal Light Command J1939 output for LDW
<u>11505VC</u>	355	<u>96120U</u>	Open 0597054 to eMV IP
<u>11297VC</u>	355	<u>96120U</u>	updating Parameter thresholds to fix Pyxis 556091, A/C HiP sensor 2609-15 faults.

Database, Version 354 (Release Date: 03/25/2021)

		-	
<u>elam_faults</u>	354		ELAM Faults

Database, Version 353 (Release Date: 03/25/2021)

51Fault 353 TPMS Faults

Database, Version 352 (Release Date: 03/02/2021)

<u>96037H</u>	352		FY 2021 BC Software R1
<u>10099VC</u>	352	96037H	597576 LANE DEPARTURE WARN Audio Mute with Switch

<u>10240VC</u>	352	96037H	597544 ENG COMPRESSION BK ROCKER SWITCH, IN LCM FOR BUS ONLY
<u>10734VC</u>	352	96037H	597072 SFC/FE Bus and to create new feature codes for MWM Euro 6 and Cummins Euro 6 Engines. 597571 597572
<u>10924VC</u>	352	96037H	727 Kernel. Update Next-Gen 12 Volt Hardware with Freescale SPC5645 microcontroller for Horizon
<u>11159VC</u>	352	96037H	Update IP 0595BZN as per H04 EV Bus
<u>11215VC</u>	352	96037H	Created release to update Radio Mute feature for removing Network modules attached to it 597294 597548
<u>11310VC</u>	352	96037H	Remove loss of comm for EV cluster network module
<u>9448VCM</u>	352	96037H	New feature for Auto High Beams 597574
<u>9449VCM</u>	352	96037H	New feature for radio fusion rumble 597575
<u>9451VCM</u>	352	96037H	Add Cruise Control Update to Hands off Detection 597517 Not yet available
<u>9453VCM</u>	352	96037H	Adaptive Cruise Control functionality 0597577 ADAPTIVE CRUISE CONT with Following Distance for Fusion 3.0
<u>9689VCM</u>	352	96037H	Add additional requirements to PTO. 597254 597266 597334
<u>9978VCM</u>	352	96037H	Feature for Parked Regen Switch Aftertreatment for SFC/FE Bus 0597543

Diamond Logic Builder Update to 15779 (Release Date 02/25/2021)

• Added support for Electronic Lift Axle Module kernel update

Database, Version 351 (Release Date: 02/24/2021)

96072J 351 Initial support for Electronic Lift Axle Module (ELAM)

Database, Version 350 (Release Date: 02/21/2021)

<u>11316VC</u>	350 96072H	Update Pressure Mismatch Monitoring for Electronic Lift Axle Module (ELAM) 597469 597470 597471
----------------	------------	--

Database, Version 349 (Release Date: 02/02/2021)

95939S 349 2021 Cluster Update Premium 40431 Base 40316

Database, Version 348 (Release Date: 01/29/2021)

<u>96037G</u>	348		FY 2021 BC Software R0.3
<u>11182VC</u>	348	96037G	Update the Function Field for Snow_Valve_Air_Solenoid_Cmd 597490 HX

Database, Version 347 (Release Date: 01/28/2021)

95863R 347 Switch Pack Kernel 25

Database, Version 346 (Release Date: 01/25/2021)

<u>95927V</u>	346		EV FY2021 BC Software R0.2
<u>10138VC</u>	346	95927V	Create Vehicle Sleep Mode for electric truck
<u>10141VC</u>	346	95927V	Regenerative Braking for electric MV 597550
<u>10162VC</u>	346	95927V	New H07 Shift Inhibit feature 597541 597566
<u>10164VC</u>	346	95927V	IP Feature for electric MV 597552

<u>10167VC</u>	346	95927V	Cluster alarm signals for electric truck
<u>10294VC</u>	346	95927V	Brake Light activation based on Vehicle Speed Deceleration for Electric vehicle 597550
<u>10296VC</u>	346	95927V	Power Adjustable Pedals for Electric Bus 595JAS
<u>10538VC</u>	346	95927V	Disable Load Shed Relay Driver Diagnostics During Key Off 597240
<u>10653VC</u>	346	95927V	726 BCM Kernel Next-Gen 12 Volt Hardware with Freescale SPC5645 microcontroller
<u>10735VC</u>	346	95927V	Update max coolant temp from 221F to 239F.
<u>10804VC</u>	346	95927V	622 Bus BCM Kernel 12 Volt Hardware with Freescale SPC5645 microcontroller
<u>10968VC</u>	346	95927V	Add Air Pressure Warning Lamp to Electric Bus
<u>9480VCM</u>	346	95927V	Update fail-safe conditions for Differential Lock. 597421 597422 5979423 597948
<u>9696VCM</u>	346	95927V	Change access level of Battery Voltage Signal for DLB
<u>9993VCM</u>	346	95927V	595BZN Air Pressure Warning Lamp on Electric Bus

Diamond Logic Builder Update to 15774 (Release Date 01/25/2021)

- Enable Switch Pack Programming Menu
- Switch Pack Kernel update to 25.

Database, Version 345 (Release Date: 01/18/2021)

<u>95952P</u>	345		Hyperion Release R0.1-2021
<u>10578VC</u>	345	95952P	Add Parameters for Rear HVAC Module in Auto Climate allow the adjustment of User Temperature Settings 597317
<u>10783VC</u>	345	95952P	Lower DLB Access Level for Road Speed Limit 597525

Database, Version 344 (Release Date: 12/18/2020)

95897CD	344		2020 R4.1 Parent Release for E79 D1 (95897C) and E79 D2 (95897D)
<u>95897C</u>	344	95897CD	E79 D1 Hyperion master release E date :- 12/18/2020
<u>9113VCM</u>	344	95897C	Vandal Lock Warning feature for HORIZON bus. 597540
<u>9131VCM</u>	344	95897C	New feature for Seatbelt Light Ind for BUS 597542
<u>9208VCM</u>	344	95897C	Open SCR (Selective Catalytic Reduction) for Horizon Bus. 0597082 requires one_of (0597003, 0597164, 0597165, 0597411, 0597535, 0597536)
<u>95897D</u>	344	95897CD	E79 Horizon Bus D2 Hyperion master release E date :- 12/18/2020
<u>9265VCM</u>	344	95897D	IP Feature for Horizon Bus 597535 597536
<u>9478VCM</u>	344	95897D	Open 0597437 to CE Horizon Bus 597437 requires one_of(0597003, 0597164, 0597165, 0597500, 0597535, 0597536)
<u>9479VCM</u>	344	95897D	Open Crank Requests feature of HORIZON Bus, 0597065 requires one_of(0597003, 0597164, 0597165, 0597411, 0597500, 0597535, 0597536, 0597552)
<u>9661VCM</u>	344	95897D	Open 0597031 to Horizon Bus.
<u>9884VCM</u>	344	95897D	Create release to open 0597108 for Horizon Bus

Database, Version 343 (Release Date: 12/03/2020)

<u>95766N</u>	343		FY 2020 BC Software R4
<u>10006VC</u>	343	95766N	Created release for Crank inhibit with PSI Engines
<u>10159VC</u>	343	95766N	Created release for Brake Light activation based on Vehicle Speed Deceleration 0595BZR Electric Vehicle

<u>10293VC</u>	343	95766N	Release to create feature Restrict Secondary Road Speed to Allison Only 0597525 requires 0597024 and 0597173
<u>10295VC</u>	343	95766N	Release for 725 OP
<u>10501VC</u>	343	95766N	Release for 621 OP
<u>10533VC</u>	343	95766N	Update filter weight of Lift Axle transducer analog inputs. Update filter weight of Lift Axle Gauges to add dampening. Parameters 3617 3618 3619
<u>8543VCM</u>	343	95766N	Created release for Lift Axle 3 Monitor pin remap for HX platform 0597494 0597495
<u>8745VCM</u>	343	95766N	To create a new transmission shifter feature 0597541 BCM PROG, SHIFT BY WIRE
<u>9114VCM</u>	343	95766N	Release created for Cruise control switch with switches located in Switch- pack.
<u>9275VCM</u>	343	95766N	To update the Teach data for 8x6 Tridem and 4x2 Super Singles Axle
<u>9276VCM</u>	343	95766N	Release created to control Radio Mute functionality base on PP.
<u>9382VCM</u>	343	95766N	Release created to activate Hazard Lights based on Highway Departure Braking feature.
<u>9442VCM</u>	343	95766N	This release is to update the A/SS Engine oil parameter feature. Also to update units of measurement to utilize C+40. Also to change PV of Engine Idle Speed to 600 RPM
<u>9632VCM</u>	343	95766N	Created new release to commonize Underhood switch 597485 597486
<u>9646VCM</u>	343	95766N	To create the separate stop turn feature for SFC/FE Bus 597523
<u>9688VCM</u>	343	95766N	Update Auto Neutral functionality to remain applied when Key newly ON
<u>9852VCM</u>	343	95766N	Remap SSC output to multiplexer for snow valve feature 597490

Diamond Logic Builder Update to 15766 (Release Date 11/30/2020)

- Enable Tire Pressure Management (TPMS) Menu.
- Restore Door Pod and LCM programming, when using Update All and Program All.

Database, Version 342 (Release Date: 09/23/2020)

<u>95856A</u> 342 He	orizon: Instrument Cluster 04.04.29
----------------------	-------------------------------------

Database, Version 341 (Release Date: 09/25/2020)

<u>95766M</u>	341		2020 R3 Parent Release
<u>7646VCM</u>	341	95766M	Lift Axle Control With LACM
<u>8785VCM</u>	341	95766M	Created Release to update PTO changes to recognize Transmission Neutral signal
<u>9197VCM</u>	341	95766M	Release for N2 Cluster Message for Low Battery and Park Brake
<u>9269VCM</u>	341	95766M	Protect Starter Manual Crank
<u>9325VCM</u>	341	95766M	To create the Cabin Heater feature for eBus program.
<u>9327VCM</u>	341	95766M	Created release for H03 Headlights
<u>9330VCM</u>	341	95766M	Created release for H03 Wheelchair Lift Interlock
<u>9337VCM</u>	341	95766M	Creating new release to update the C-Rule to open 0595ABP for eBus IP.
<u>9338VCM</u>	341	95766M	Created release to open feature 0595ALH for H03 platform.
<u>9340VCM</u>	341	95766M	To create the new Park Light feature for eBUS.
<u>9341VCM</u>	341	95766M	Creating new release to update the C-Rule to open 0595BAZ for eBus IP.
<u>9343VCM</u>	341	95766M	To Create new feature EBus Sleep Functionality.
<u>9344VCM</u>	341	95766M	Release for IP Feature for EBus
<u>9357VCM</u>	341	95766M	To create No Idle Heater feature without Condensation module request.

<u>9365VCM</u>	341	95766M	New release to create Grid Management feature for eBus
<u>9445VCM</u>	341	95766M	Created release to not process any Brake Switch fault if there is External Brake message from ABS Module
<u>9460VCM</u>	341	95766M	Created release for eBus Exterior Light Check
<u>9463VCM</u>	341	95766M	Release to create new feature for the Regenerative Braking to send messages to VCU
<u>9551VCM</u>	341	95766M	724 OP Update
<u>9552VCM</u>	341	95766M	OP Update to 620
<u>9594VCM</u>	341	95766M	Release to create feature to transmit Air Compressor Disable Message to VCU
<u>9684VCM</u>	341	95766M	Realease to create new feature for Road Speed Limiting.
<u>9690VCM</u>	341	95766M	Created new release to change diagnostic threshold value for Hydromax Pressure/Flow Switch.
<u>9707VCM</u>	341	95766M	To create a new feature for mapping Park Brake Indicator to WL12.
<u>9708VCM</u>	341	95766M	Release to Create New Feature for Traction Control with warning light
<u>9709VCM</u>	341	95766M	Release creating to map seat belt indicator Warning Lamp to WL23
<u>9710VCM</u>	341	95766M	To create similar feature to 0595KAT
<u>9711VCM</u>	341	95766M	Release creating to map ABS indicator Warning Lamp to WL16

Diamond Logic Builder Update to 15749 (Release Date 09/15/2020)

- Hide TPMS Menu (Under Development)
- Disabled Switch Pack and Door Pod Programming

Database, Version 340 (Release Date: 08/18/2020)

|--|

Diamond Logic Builder Update to 15745 (Release Date 08/19/2020)

- Enhanced Login
- Removed Switch Pack Programming Menu Item

Database, Version 339 (Release Date: 08/13/2020)

<u>95593Y</u>	339		2020 R2.1 Parent Release
<u>9865VCM</u>	339	95593Y	DLB Filter Rule Update for MX16

Diamond Logic Builder update to 15733 (Release Date 06/26/2020)

- Update to switch pack flashing routine
 - Switch Pack module update function removed from "Update Software" routine
 - New menu item, "Switch Pack Programming", added under "Tools" menu
 - Updates all switch pack modules to Kernel 22
 - Assigns address during software update/flash
 - Added address modification screen
 - Dialog added with link to iKNow article IK0800590
 - Dialog added with instructions to clear DTCs after using the "Switch Pack Programming" menu option
- Update link to change log

Database, Version 338 (Release Date: 06/26/2020)

<u>95689J</u> 338	(Hyp Component Data Rls FY20R1)
-------------------	---------------------------------

Database, Version 337 (Release Date: 06/26/2020)

<u>95562T</u>	337		2020 R2 BC Software Parent Release
<u>6399VCM</u>	337	95562T	To change the load shed relay fault message description for both active high and active low relay output.
<u>7107VCM</u>	337	95562T	Created release to define fault information for optional switches in the LCM.
<u>7111VCM</u>	337	95562T	Release to create 3rd Axle for Axle Temp
<u>7324VCM</u>	337	95562T	Release to update Auto Headlights ON Wait Time to 1 second
<u>7453VCM</u>	337	95562T	Release to create Namco Transfer Case Electrical Control feature
<u>7766VCM</u>	337	95562T	To create new feature Air solenoid controlled Snow Valve.
8009VCM	337	95562T	Created new release to update code block.
<u>8144VCM</u>	337	95562T	To create new feature for Lane Keep Assist.
<u>8251VCM</u>	337	95562T	Created release for Aux Trans NV Ratio Comms as per Pyxis
<u>8694VCM</u>	337	95562T	Created new feature for Steering Performance
<u>8936VCM</u>	337	95562T	Release for new Load Shed strategy. Kernel will periodically wake up so application can check to see if load shed is needed
<u>8997VCM</u>	337	95562T	This release is created to update a parameter value for A26 engine.
<u>9004VCM</u>	337	95562T	This release is created to add Off Road drive mode.
<u>9020VCM</u>	337	95562T	Created release to add load shed level 2 check for Heated Windshield
<u>9079VCM</u>	337	95562T	Release for Hands Off Detection Warning and Disabling
<u>9165VCM</u>	337	95562T	This release is created to map DLB parameter.
<u>9173VCM</u>	337	95562T	To update feature 0597488 to remove DRL and create a new feature for enabling DRL
<u>9211VCM</u>	337	95562T	Created release to fix to fix Open fault occurring randomly on Pressure sensor
<u>9253VCM</u>	337	95562T	Created release for E44 Trans shifter to open 0597444 for MV/HV platform
<u>9427VCM</u>	337	95562T	Created release to enable PGN 57344, 65264, 65089 and 65273 on Body Bus
<u>9512VCM</u>	337	95562T	723 OP Update

Database, Version 336 (Release Date: 06/26/2020)

<u>95689M</u>	336		(FY 2020 BC Software R1.3)
<u>9705VCM</u>	336	95689M	Release to update Remote SS to turn on Ignition grid after requesting Emergency Pump

Diamond Logic Builder update to 15720 (Release Date 06/03/2020)

- Update to Gen 4 emitter (600 Series Kernel)

Database, Version 335 (Release Date: 06/01/2020)

<u>95629B</u>	335		2020 R1.2 Software Parent Release
<u>7596VCM</u>	335	95629B	OP Update 619

<u>8366VCM</u>	335	95629B	Update to Remote SS as per Pyxis 501915
<u>9416VCM</u>	335	95629B	Release for 722 OP Update
<u>9423VCM</u>	335	95629B	Release to update the engine ramp threshold in the Auto Start Stop feature from a constant to a parameter
<u>9474VCM</u>	335	95629B	Update the C-Rule of feature 0597319 to make it available for LT platform

Diamond Logic Builder update to 15717 (Release Date 04/29/2020)

- Fixed DLB Simulator
- Fixed issue with templates adding undesired modules
- Added prompt to clear DTC's after programming

Database, Version 334 (Release Date: 04/27/2020)

<u>95629N</u>	334		95629N (FY 2020 BC Software R1.1.1)
<u>9454VCM</u>	334	95629N	Update the Checksum data for addition of Sample 1 to Sample 5 data to the PGN

Database, Version 333 (Release Date: 04/17/2020)

<u>95618Z</u>	333		95618Z: FY 2020 BC Software R1.1
<u>9180VCM</u>	333	95618Z	721 OP Update
<u>9407VCM</u>	333	95618Z	Release for Knock Sensor fault logging

Database, Version 332 (Release Date: 03/02/2020)

<u>95485B</u>	332		2020 R1 BC Software Parent Release
7008VCM	332	95485B	Created release to add DTE fuel tanks for HX vehicle
<u>7047VCM</u>	332	95485B	Created release for CAN LED Headlight functionality
<u>7700VCM</u>	332	95485B	Release to create Snow Plow Lights feature compatible with CAN LED Headlights.
<u>7701VCM</u>	332	95485B	CAN based Marker Lights
<u>7704VCM</u>	332	95485B	Created release for Directional Turns E36
<u>7900VCM</u>	332	95485B	Release for New Service Brake Switch feature
<u>8176VCM</u>	332	95485B	To create new E63 Transmission Retarder feature
<u>8243VCM</u>	332	95485B	To create new feature for Transfer case PTO
<u>8294VCM</u>	332	95485B	To create a new Underhood Lighting feature.
<u>8371VCM</u>	332	95485B	Release to create new feature for Modesty lighting
<u>8594VCM</u>	332	95485B	Created release to control a secondary work light on HV/MV vehicles
<u>8602VCM</u>	332	95485B	To create new Active Ride Height Control feature.

Database, Version 331 (Release Date: 02/06/2020)

5368W/ 331 HV	IVAC
550000	

<u>95485A</u>	329		2020 R0.2 BC Software Parent Release
<u>8364VCM</u>	329	95485A	OP Update 720
<u>8935VCM</u>	329	95485A	Release to update Network Module to Support DM13 message stop broadcast

Database, Version 328 (Release Date: 01/06/2020)

<u>95450Z</u>	328		2020 R0.1 BC Software Parent Release
<u>9024VCM</u>	328	95450Z	Update to Remote SS Features to not consider Hood Switch when shutting off engine

Database, Version 327 (Release Date: 01/06/2020)

<u>95368U</u>	327		Premium cluster 04.04.29
---------------	-----	--	--------------------------

Database, Version 325 (Release Date: 12/13/2019)

95368T 326 Base Cluster 4.03.10	
---------------------------------	--

Database, Version 325 (Release Date: 12/13/2019)

<u>95368K</u>	325		2019 R6 BC Software Parent Release
<u>7735VCM</u>	325	95368K	To create new feature for Autotherm No-Idle PCA
<u>7767VCM</u>	325	95368K	Creating release for in cab panic. Release also includes moving separate panic functionality
<u>8245VCM</u>	325	95368K	Seat Belt Range Inhibit Feature
<u>8595VCM</u>	325	95368K	To Remove fault code 2000:19
<u>8612VCM</u>	325	95368K	E36 Halogen Headlight functionality with Plow
8639VCM	325	95368K	To create new feature for A38 Engine.
<u>8766VCM</u>	325	95368K	To add N2 faults in Hyperion

Database, Version 324 (Release Date: 11/26/2019)

<u>95368J</u>	324		2019 R5.2 BC Software Parent Release
<u>8356VCM</u>	324	95368J	OP Update 719
<u>8385VCM</u>	324	95368J	Created release to fix removal of LP switch - With Bi-Metal Fan
<u>8707VCM</u>	324	95368J	MIL Lighting

Database, Version 323 (Release Date: 11/26/2019)

<u>8953VCM</u>	323	95368Y	Created release to fix Bunk Blower Shut Off problem as per deviation document EES-SE-I-6002-11-Dev Ver1.0
----------------	-----	--------	---

Database, Version 322 (Release Date: 11/19/2019)

<u>95368V</u>	322		2019 R5.1 BC Software Parent Release
<u>8949VCM</u>	322	95368V	Fix for Cruise Switch Dropout with Load Surge

Diamond Logic Builder update to 15704 (Release Date 11/25/2019) - Added log in enhancements

Database, Version 321 (Release Date: 10/17/2019)

<u>95286D</u>	321		FY 2019 BC Software R5
<u>5683VCM</u>	321	95286D	Release to fix liftgate timeout issue
<u>7110VCM</u>	321	95286D	Release to create Axle Loading with Tridem feature
<u>7762VCM</u>	321	95286D	HX Headlights
<u>7999VCM</u>	321	95286D	Created release to remap Sleeper pin to a new output
<u>8073VCM</u>	321	95286D	To Update Filter Rule and Solenoid multiplexer
<u>8143VCM</u>	321	95286D	Add-on feature to turn off DRL when vehicle speed is at or below 5mph.
<u>8284VCM</u>	321	95286D	This release is to change the read and write access of programmable parameter Axle_Load_Rear_Error_Offset
<u>8285VCM</u>	321	95286D	This is Release is to make 0595BNA feature compatible with HX by adding IP feature 0595JBA to it.
8531VCM	321	95286D	To Open up Feature 0597270 (Ammeter) to IP 0597003

Database, Version 320 (Release Date: 09/09/2019)

<u>95286M</u>	320		95286M : FY 2019 BC Software R4.1
<u>8703VCM</u>	320	95286M	To update Network Modules to send PGN 65321, 64973 and 65274 to support DVIR in Horizon

Database, Version 319 (Release Date: 08/23/2019)

<u>95156A</u>	319		4.4.10 Premium cluster
---------------	-----	--	------------------------

Database, Version 318 (Release Date: 08/23/2019)

95095Z 318 Base Cluster 04.03.07

Diamond Logic Builder update to 15686 (Release Date 08/23/2019)

Added Campaign to remove 597178

Database, Version 317 (Release Date: 08/21/2019)

<u>95239F</u>	317		FY 2019 BC Software R4
<u>R4_2019</u>	317	95239F	R4_2019 Parent for R4 Releases
<u>7308VCM</u>	317	R4_2019	To update Filter rules for LT sleeper features and added on 0597164.

7593VCM	317	R4 2019	OP Update 618
7599VCM	317	 R4 2019	OP Update 718
<u>7873VCM</u>	317	 R4_2019	To create Electric City Horn code to transmit request status over J1939 Body Bus Network
<u>7874VCM</u>	317	R4_2019	To create Electric City Horn code for HZN platform to transmit request status over J1939 Body Bus Network
<u>7875VCM</u>	317	R4_2019	Release to transmit service door request status to N2 on body builder 250k network
<u>7876VCM</u>	317	R4_2019	Update PWL 595 Code(s) to transmit request status over J1939 Body Bus Network
<u>7877VCM</u>	317	R4_2019	Created release to update Emergency Exit Door 595 Code(s) to transmit request over J1939 Body Bus network.
<u>7878VCM</u>	317	R4_2019	To create Directional Turns Code to transmit request status over J1939 Body Bus Network.
<u>7879VCM</u>	317	R4_2019	Created release to transmit High Beam Switch Request Status over J1939 Body Bus Network
<u>7880VCM</u>	317	R4_2019	Release to update Park Lights 595 Code(s) to transmit request status over J1939 Body Bus Network.
<u>7881VCM</u>	317	R4_2019	Update Crossing Gate 595 Code(s) to transmit request status over J1939 Body Bus Network
<u>7882VCM</u>	317	R4_2019	Update Stop Arm 595 Code(s) to transmit request status over J1939 Body Bus Network
<u>7892VCM</u>	317	R4_2019	Created release to update Neutral Confirmation feature to transmit request status over J1939 Body Bus network.
<u>7894VCM</u>	317	R4_2019	Release to update Turn Signals 597 Code to transmit request status over J1939 Body Bus Network.
<u>7895VCM</u>	317	R4_2019	Release created to transmit High Beam Switch Request Status over J1939 Body Bus Network
<u>7897VCM</u>	317	R4_2019	Created Release to transmit Conditioned_Brake_Switch_Signal over J1939 Body Bus Network.
<u>7899VCM</u>	317	R4_2019	Release created to update wheelchair transmit request status over j1939 Body Bus Network.
<u>7945VCM</u>	317	R4_2019	Created release for HVAC removal of LP switch for LT/RH
7983VCM	317	R4_2019	Release for CE Bus version of OTA
<u>7984VCM</u>	317	R4_2019	Release created to update wheelchair transmit request status over j1939 Body Bus Network.
8092VCM	317	R4_2019	6XX Grid Changes for OTA
8154VCM	317	R4_2019	Updated diagnostics for load shed relay driver
8283VCM	317	R4_2019	Release to enable Cluster Trip - Idle - Fuel/Hrs Enable
8346VCM	317	R4_2019	Added 0595BDD to CRule-PWL-1-Option5-BUS for 0595BNG
<u>8379VCM</u>	317	R4_2019	Release to add CAL-CON teach data

Database, Version 316 (Release Date: 08/02/2019)

<u>95239H</u>	316		FY 2019 BC Software R3.1
<u>8453VCM</u>	316	95239H	Release to updated dome light features to be sheddable.
<u>8457VCM</u>	316	95239H	Release to add in hysteresis parameters to load shed

<u>95095N</u>	314		FY 2019 BC SOFTWARE R3
<u>7067VCM</u>	314	95095N	Created release for Differential lock Three switches, Three axles
<u>7109VCM</u>	314	95095N	Release created for 3 Lift Axle Control features
<u>7413VCM</u>	314	95095N	To update combined Stop Turn feature by adding Turns Override Hazard Parameter
<u>7529VCM</u>	314	95095N	Release for Fuel Tank Distance to Empty feature
<u>7595VCM</u>	314	95095N	617 OP Update
<u>7598VCM</u>	314	95095N	717 OP Update
<u>7600VCM</u>	314	95095N	513 OP Update
<u>7606VCM</u>	314	95095N	Release to create Body Controller features For Gen2
<u>7607VCM</u>	314	95095N	Created release for new Gen4 Controller features
<u>7608VCM</u>	314	95095N	Created release for new Horizon Controller feature
<u>7655VCM</u>	314	95095N	Created release for Drain Valve Mux Software
<u>7768VCM</u>	314	95095N	E40 Crank Request Comms
<u>7784VCM</u>	314	95095N	New Feature for Autotherm
<u>8070VCM</u>	314	95095N	Created release to fix Pyxis 493110

Diamond Logic Builder update to 15680 (Release Date 06/26/2019)

- Added pop up message for processing Campaigns before programming

Database, Version 313 (Release Date: 05/31/2019)

<u>95156M</u>	313		95156M : FY 2019 BC Software R2.3
<u>8322VCM</u>	313	95156M	Release to revert 0597361 back to previous release VCM-5617

Diamond Logic Builder update to 15678 (Release Date 05/24/2019)

- Enhanced diagnostics
- Message regarding simulator support for ESC Kernels greater than 716.

Database, Version 312 (Release Date: 05/24/2019)

<u>95156M</u>	313		95156M : FY 2019 BC Software R2.3
8322VCM	313	95156M	Release to revert 0597361 back to previous release VCM-5617

Database, Version 311 (Release Date: 04/25/2019)

<u>94933W</u>	311		FY 2019 BC Software R2.1
6650VCM	311	94933W	Remote Start Stop fix.
<u>7011VCM</u>	311	94933W	Grid Control / Crank Inhibit / Key Switch Re-Architecture for "Click - No Crank", Crank Inhibit enhancements, other numerous Architectural improvements and fixes.
<u>7014VCM</u>	311	94933W	Created release to add N2-ELD Indicator Horizon Architecture.
<u>7395VCM</u>	311	94933W	Created release to update Auto SS features as per change in Grid architecture
7430VCM	311	94933W	Release for N2 OTAPM grid management/crank inhibit implementation
<u>7594VCM</u>	311	94933W	716 OP Update

Database, Version 310 (Release Date: 04/25/2019)

950955 310 Stalk shifter 56 v3	
--------------------------------	--

Database, Version 309 (Release Date: 04/25/2019)

<u>95039k</u>	309		LCM 18
---------------	-----	--	--------

Diamond Logic Builder update to 15666 (Release Date 05/01/2019)

- In an effort to keep modules at compatible kernels, level II and III users can no longer select a single module bupdate. The only option is, "Update All"
- In an effort to keep modules at compatible kernels, level II and III users can no longer select a single module bprogram. The only option is, "Program All"
- The EULA is available in the Help menu
- The registration library has been updated
- Lift Axle 3-gauge feature is now supported

Database, Version 308 (Release Date: 04/25/2019)

95039J 308 Mux 17

Database, Version 307 (Release Date: 04/25/2019)

<u>CMA_OPs</u>	307		This release contains all previous operating programs, STCs and module definitions for CMA-based modules (i.e. Aware, VSM, VID)
----------------	-----	--	---

Database, Version 306 (Release Date: 04/25/2019)

<u>94889Y</u>	306		FY 2019 BC Software R2
<u>6680VCM</u>	306	94889Y	Fix Allison Transmission transition issue. 597361
<u>7096VCM</u>	306	94889Y	Release created to update Rear HVAC Bergstrom feature when Auto Start Stop enabled 597041 597250
<u>7409VCM</u>	306	94889Y	Resolve issue with Wheel Chair lift timimg. 595BWW
<u>7410VCM</u>	306	94889Y	Created release to add DLB Wig Wag for Horizon. 597448 v597449 For NGV platform this internal DLB signal provides the ability to disable the headlights wig wag. For Horizon platform this internal DLB signal provides the ability to enable the headlights wig wag.
<u>7411VCM</u>	306	94889Y	Headlights DLB changes. Headlight and Parklight Failsafe Handling 597077 597184 597410
<u>7412VCM</u>	306	94889Y	Add DLB signals for Power Door Locks. 597136 Door_UnLock_Request, Door_Lock_Request
<u>7667VCM</u>	306	94889Y	Created release for Separate Stop, Turns feature for USPS Tail Lights 597026 Added Turns Override parameter, 597054, 597136 added contact, 597454 TURN SIGNALS/BRAKE WITH SEPARATE STOP AND TURNS
<u>7772VCM</u>	306	94889Y	Updated ELC to add DLB and RKA request.

Database, Version 305 (Release Date: 03/26/2019)

<u>95039M</u>	305		Hyperion Fy2019-R1.1
7841VCM	305	95039M	Resolve timing issue on 0595AGX Bus Pupil Warning Lights

Database, Version 304 (Release Date: 03/04/2019)

<u>94889W</u>	304		BC Software R1
<u>6653VCM</u>	304	R1_2019	Change to beep correct alarm when Wheel Based Vehicle Speed surpasses speed threshold and to change the type of PDL_Lock_Switch_Ind_Cmd. 597025
<u>6654VCM</u>	304	R1_2019	To create a Power Output Signal Definition similar to SD-DO-Open- Sol_1_Gen2 to enable setting overcurrent failure SPN for 1A power outputs 597261 597262 normaly open
<u>6679VCM</u>	304	R1_2019	Fix Snow Plow Light issues by adding Headlight_Steady_State instead of Headlight_State, Plow Lights button latching condition, fault logging scenario and Plow switch telltale activates by ELC 597301 597487
<u>7049VCM</u>	304	R1_2019	To create a logic for Lighting Control For Hazards and Turns using DLB 0597026 added Turns Override parameter 3347, 597136 added Hazard_Light_DLB_Req
<u>7316VCM</u>	304	R1_2019	Created release for Lift Axle 3 implementation both for Virtual and Aux Gauges 597400 597403
<u>7320VCM</u>	304	R1_2019	715 BCM Kernel Truck 12 Volt Hardware with Freescale SPC5645 microcontroller
<u>7321VCM</u>	304	R1_2019	616 BCM Kernel Bus 12 Volt Hardware with Freescale SPC5645 microcontroller
<u>7322VCM</u>	304	R1_2019	To Create new feature for Dual Cont Aux Load # 5 Switches 597447
<u>7339VCM</u>	304	R1_2019	To provide a 0 second park brake alarm Suspend timer 597446 requires one_of (0597003, 0597164, 0597165, 0597500, 0597552)
<u>7341VCM</u>	304	R1_2019	Update Park Lights control logic to add Park Light DLB request. Update Park Lights control logic to add Park Light DLB request.
<u>7370VCM</u>	304	R1_2019	Add Park Brake Alarm interlock Description: The Park Brake Alarm sounds/beeps if the driver turns the key off and opens the door while the park brake is not set. The alarm stops beeping if: key state changes from Key off position, alarm timer expires, Park brake set. The Park brake alarm is suspended for certain amount of time when Brake pedal is pushed.
<u>7618VCM</u>	304	R1_2019	To update Remote engine speed control feature for SA 0x07 597424 597425
<u>7619VCM</u>	304	R1_2019	Resolve issue on 597445 LANE DEPARTURE SYS {OnLane2}

Database, Version 303 (Release Date: 01/16/2019)

<u>7370VCM</u>	304	R1_2019	Add Park Brake Alarm interlock Description: The Park Brake Alarm sounds/beeps if the driver turns the key off and opens the door while the park brake is not set. The alarm stops beeping if: key state changes from Key off position, alarm timer expires, Park brake set. The Park brake alarm is suspended for certain amount of time when Brake pedal is pushed.
----------------	-----	---------	---

<u>94851F</u>	302		94851F: BC Software R6 2018
<u>5860VCM</u>	302	94851F	Implement Wabco OnLane2 Lane Departure Warning System {OnLane2} 597445
<u>6203VCM</u>	302	94851F	Add new Mirror Heat Timeout value 597006 597061 597006 597109 597388 597418 597420 Parameter 3454
<u>6934VCM</u>	302	94851F	GZ Transmission PRNDL and Trans Warning Light. 597430 597431 597444
<u>7013VCM</u>	302	94851F	Update Work Lights Parameter for Off Speed as per new requirement 597008 0597493 Parameter 2568
<u>7026VCM</u>	302	94851F	New PTO switch for new BCM features 597442 597443 Add new PTO Switch labeling
<u>7069VCM</u>	302	94851F	Add Motor Stall Diagnostics to Power Adjustable Pedal functionality 595JAJ

Database, Version 301 (Release Date: 11/06/2018)

<u>94793N</u>	301		Premium Cluster Software 04.04.05
---------------	-----	--	-----------------------------------

Database, Version 300 (Release Date: 11/06/2018)

<u>94793M</u>	300		Base Cluster 04.03.05
---------------	-----	--	-----------------------

Database, Version 299 (Release Date: 11/05/2018)

<u>94865R</u>	299		FY 2018 BC Software R5.1 for HX PTO Feedback Silverback
<u>7390VCM</u>	299	94865R	Created release to fix HX PTO Feedback Silverback issue.

Database, Version 298 (Release Date: 10/29/2018)

<u>94865B</u>	298	Initial support for automatic HVAC
---------------	-----	------------------------------------

Database, Version 297 (Release Date: 10/26/2018)

<u>94771L</u>	297		94771L: FY 2018 BC Software R5
5735VCM	297	94771L	To create new features(6xx & 7xx) for load indication on the Durastar
			model with Hendrickson Primaax suspension and a single axle.
<u>6217VCM</u>	297	94771L	New GZ Transmission Downhill Speed Control Feature
6299VCM	297	94771L	Release to create Maneuvering Mode feature for E40 program.
6306VCM	297	94771L	Release for drive mode selection features
<u>6445VCM</u>	297	94771L	Created release to transmit seat belt status to engine and broadcast PGN
			57344
6656VCM	297	94771L	This release is created so that the Feature 0597309 is available on the LT
			platform
6701VCM	297	94771L	Created release to integrate Hazard Switch for E43 program also replaced
			Hazard_Switch_Signal to Hazard_Switch_Signal_Msg for 0595BXS and
			0597026 features
6717VCM	297	94771L	Created release for Global LT - Adapt 0597346 to allow this feature to run
			on LT/RH 0597003 IP Feature

<u>6779VCM</u>	297	94771L	Created release to transmit AC Comp status and pressure over CAN
6784VCM	297	94771L	Created release for new 0595 feature to change slope of PAM module for
			PSI Engines
<u>6787VCM</u>	297	94771L	Release created for Global LT - Adapt 0597335 to allow this feature to run on LT/RH 0597003 IP Feature
<u>6792VCM</u>	297	94771L	Release created for new Programmable Parameter to overwrite Engine Oil Temperature for Auto Start Stop
6826VCM	297	94771L	To create Grid control feature for non-load shed vehicles
<u>7017VCM</u>	297	94771L	To change the Fill Order of Filter Minder Gauge from 8005 to 8007
<u>7022VCM</u>	297	94771L	Addressing Pyxis concern 486991
<u>7246VCM</u>	297	94771L	PAM updates per new requirements

Diamond Logic Builder update to 15650 (Release Date 10/24/2018)

- Updated HVAC recovery mode to only be available when an HVAC module is not detected
- Support adjustment of the cluster volume on new models, under tools menu
- Support detection and programming of Automatic Temperature Control variants of the HVAC control head
- Support detection of additional HX cluster part numbers

Database, Version 296 (Release Date: 10/24/2018)

<u>94865A</u>	296		94865A: FY 2018 BC Software R4.4
<u>7299VCM</u>	296	94865A	714 OP Update
<u>7333VCM</u>	296	94865A	Application interface changes for 5th Switch Pack. (Pyxis Concern 490505)
<u>7333VCIVI</u>	296	94805A	Application interface changes for 5th Switch Pack. (Pyxis Concern 4905

Database, Version 295 (Release Date: 10/09/2018)

<u>94851M</u>	295		FY 2018 BC Software R4.3
<u>7325VCM</u>	295	94851M	Created release to add Adjustable Pedal Switch missing slot type

Database, Version 294 (Release Date: 09/24/2018)

<u>94771K</u>	294		94771K: FY 2018 BC Software R4.2
<u>6778VCM</u>	294	94771K	713 OP Update
<u>7018VCM</u>	294	94771K	Open 0597101 to MV/HV Models
<u>7019VCM</u>	294	94771K	Update Parklights to send SPN 2378 "Tractor Marker Light" for LCM Backlighting
<u>7023VCM</u>	294	94771K	This release is created to add 0597184 on E43
<u>7035VCM</u>	294	94771K	Release to allow feature 0595BDD to be added in the Inclusion Rule.

Diamond Logic Builder update to 15639 (Release Date 08/29/2018)

- Support new bootloader in simulator

- Support new user registration format
- Resolve switch pack issue

Database, Version 293 (Release Date: 08/23/2018)

<u>94648N</u>	293		Parent Release for R4 2018
<u>6261VCM</u>	293	94648N	To create a new feature for One Door Pod for Power Window and Power Lock using Driver Front Module
<u>6263VCM</u>	293	94648N	Created release for One Door Pod Heated Mirrors using Driver Front Module
<u>6264VCM</u>	293	94648N	To create a new feature code for One Door Pod for Power Mirrors using Driver Front Module
<u>6301VCM</u>	293	94648N	Release to create new Snow Valve feature for H-Bridge
<u>6345VCM</u>	293	94648N	Auto Headlight (New Twilight)
6398VCM	293	94648N	Auto HVAC Teach Functionality
6402VCM	293	94648N	Release created for Exhaust Brake feature to support new requirement
<u>6403VCM</u>	293	94648N	Created release for MWM Engine Type feature for Horizon
<u>6416VCM</u>	293	94648N	To create new feature for Diagnostic Command FE, SFC platform
6459VCM	293	94648N	Create a new IP for E43 program
<u>6460VCM</u>	293	94648N	To create Air Pressure Gauges with no Door Switch
6461VCM	293	94648N	Created release to update DLB Filter Rules for E43 required features
<u>6472VCM</u>	293	94648N	712 OP Update
6532VCM	293	94648N	To fix BUS PWL issue
<u>6533VCM</u>	293	94648N	Adding brake switch OOR fault debounce also update healing count from 20 to 40.
<u>6546VCM</u>	293	94648N	Created release for Differential Lock Single Switch to create new features
			for supported one, two and three monitors
<u>6547VCM</u>	293	94648N	Created release for Driver Controlled Locking Differential Monitor - 2 Switches
<u>6591VCM</u>	293	94648N	This release is created a new Windshield Wiper feature Without Relay Diagnostics
<u>6592VCM</u>	293	94648N	Created release to add 2-Speed Axle for E43 program
<u>6673VCM</u>	293	94648N	Created a release for Redundant Flasher Switch. Two Pyxis concern #477452 and #476202 were reported and they are addressed under 6673VCM. As 5874VCM is not released, for simplicity 5874VCM is replaced by 6673VCM. (Note that initially Samveg Shah used 5874VCM to complete the initial development).
6700VCM	293	94648N	Release created to open 0595BWR upto 0595BJU
<u>6707VCM</u>	293	94648N	Release created for Abigail active student detection for BUS
<u>6777VCM</u>	293	94648N	615 OP Update
<u>6817VCM</u>	293	94648N	Panel definition and panel priority updates
6896VCM	293	94648N	Update 0597425 for failsafe condition per requirement.
<u>6897VCM</u>	293	94648N	created release to update 0597132 and 0597133 features to support SPNs 3460 and 3461

Database, Version 292 (Release Date: 08/23/2018)

<u>94739J</u>	292		R4 Parent for ACC/CMS cluster alarms on Horizon cluster
<u>6699VCM</u>	292	94739J	Release to add default and add-on CALCON values for CMS Alerts Volume CALCON.

Database, Version 291 (Release Date: 07/13/2018)

<u>94716R</u>	291		Switch version 2 passenger door pod software
---------------	-----	--	--

Database, Version 290 (Release Date: 07/06/2018)

<u>94583C</u>	290		Parent Release for R3 2018
4155VCM	290	94583C	Release created to update the logic for LOWW request
<u>5391VCM</u>	290	94583C	Created to fix ELC to work properly with non LED headlight features and add Wig-Wag status as an additional interlock for activating/deactivating ELC
<u>5851VCM</u>	290	94583C	Release to create Air Suspension virtual gauge and auxiliary gauge features
<u>5869VCM</u>	290	94583C	Release to create Lift Axle 1 and 2 virtual gauge and auxiliary gauge features
<u>5957VCM</u>	290	94583C	Created release to transmit HX turn signal CAN message
<u>6122VCM</u>	290	94583C	Release to revise OP to 711
<u>6136VCM</u>	290	94583C	Release created to add Economy Monitor Tank sizes for Fuel
<u>6142VCM</u>	290	94583C	Release for new and enhanced Hydromax feature for MV/HV
<u>6144VCM</u>	290	94583C	Release for new Hydro Max feature for NGV Platform
<u>6259VCM</u>	290	94583C	Changes to Key Switch and Grid Control for Horizon architecture ((Pyxis 464289).
6265VCM	290	94583C	Release created to update load shed messages for 500k NGV platform
<u>6368VCM</u>	290	94583C	Created Release to enable BCM teach data bit for displaying message about Engine Throttle
<u>6397VCM</u>	290	94583C	OP update for 614 kernel
<u>6474VCM</u>	290	94583C	Release created to add Economy Monitor Tank sizes for DEF
<u>6545VCM</u>	290	94583C	To fix engine retarder from forcing the brake lights off
<u>6825VCM</u>	290	94583C	Release to open 0595BDC with IP 0595BJH and 0595BBU.
<u>6846VCM</u>	290	94583C	New Feature to support Super Products Request (Engine PTO and Trans PTO)

Database, Version 289 (Release Date: 07/05/2018)

<u>94672G</u>	289		R2.3 Auto Start Stop Hyperion Release
<u>6790VCM</u>	289	94672G	Click No Crank update for Horizon Auto SS

Database, Version 288 (Release Date: 06/13/2018)

<u>94672E</u>	288		FY18 R2.2 - Auto Neutral	
<u>6534VCM</u>	288	94672E	Release to open the Auto Neutral features for LT.	
Database, Version 287 (Release Date: 06/06/2018)				
<u>94648P</u>	287		Door pod 2.0	

Database, Version 286 (Release Date: 05/14/2018)

<u>94627C</u>	286		Base Cluster 04.03.03
---------------	-----	--	-----------------------

Database, Version 285 (Release Date: 05/09/2018)

=		
<u>94605S</u>	285	Door Pod 1.9

Diamond Logic Builder update to 15633 (Release date 05/03/2018)

- Support HX odometer programming;
- Support programming clusters @ 250K
- Support door pod module update programming
- Support Predictive Cruise Control module update programming
- Correct Body Controller connector numbering for J6 (1606) and J7 (1607)

Database, Version 284 (Release Date: 04/30/2018)

284		94472P 2018 R2 Master Parent Release
284	94472P	Release for creating new feature similar to 0595ALK AUXILIARY TRANS
284	94472P	Created release to update 0597013 feature as per EES-SE-I-5011-02
284	94472P	Created release to open remaining signals for Ladder Logic.
284	94472P	Create new feature for Message Waiting Warning Lamp
284	94472P	Created release to replace HVAC_High_SuperHeat_Temp_Threshold and
		HVAC_Low_SuperHeat_Temp_Threshold parameter values from 75C to 62C
284	94472P	Release created to update Healing count for feature 0597319
284	94472P	Release to add new feature for Adjustable pedal
284	94472P	To create a feature similar as 0595AEV for MV/HV
284	94472P	Created release to support 0597276, 0597306 feature for LT/LS platform
284	94472P	Release to add new PV to update the Compressor ON Time from 7 sec to 1 sec. This change is limited to 0597058,0597168 and 0597387 but not to Gen2/Gen4 features.
	284 284 284 284 284 284 284 284 284 284	284 94472P 284 94472P

Database, Version 283 (Release Date: 04/27/2018)

<u>94566M</u>	283		R2.1 94566M has been pulled for R2.1, planned E Date of 4/25/2018.
<u>6300VCM</u>	283	94566M	Release created to open Allison 3K/4K feature for LT platform
<u>6370VCM</u>	283	94566M	Release to address Pyxis concern 469134 for Remote SS
<u>6437VCM</u>	283	94566M	To create a new feature to remap the LED Headlight Parklight Output from HBridge to 10A19

Database, Version 282 (Release Date: 04/23/2018)

046055	202	Base cluster 4 03 02
<u>94605E</u>	282	Base cluster 4.03.02

Database, Version 281 (Release Date: 03/23/2018)

<u>94605B</u>	281		Hyperion Component Data FY18R5
---------------	-----	--	--------------------------------

Database, Version 280 (Release Date: 03/23/2018)

<u>94472N</u>	280		94472N 2018 R1.1
6064VCM	280	94472N	Update Coolant Temperature gauge to change Alarm delay time
<u>6169VCM</u>	280	94472N	Create a new feature with single door pod with passenger side door pod replacing the driver side door pod.
<u>6213VCM</u>	280	94472N	Key Switch and Grid Control Key Switch Fault Handling and Fault Logging changes (Pyxis 464289).
<u>6219VCM</u>	280	94472N	Release to update OP to 613
6357VCM	280	94472N	Release to change pin from DIN 17 to DIN 18 for SAAR Brake

Diamond Logic Builder 15622 (Release Date: 03/21/2018)

- Correct several missing gauge cluster images, in Cluster view
- Correct several incorrect gauge cluster indicators, in Cluster view
- Enhanced programming timing
- Tricolor Switch enhancements
- Clear DTC's from Switch-Pack, LCM and Door Pods at the end of Module programming

Database, Version 277 (Release Date: 03/18/2018)

Database, Version 276 (Release Date: 03/08/2018)

Database, Version 275 (Release Date: 02/23/2018)

Diamond Logic Builder 15611 (Release Date: 02/19/2018)

- Resolve graphic issues for Gasoline and Propane Bus Fuel Gauge and Seat Belt indicator
- Enhanced Odometer programming to prevent Odometer value from changing after it has been set
- HVAC module flashing included in 'Update All' procedure
- Add color options to LT, RH, HV and MV switches during diagnostics
- Resolve graphic issues for brake air indicator, snow valve, aux voltage gauge, and RPM graphics

Database Version 272 (Release Date: 01/21/2018)

Database Version 271 (Release Date: 12/30/2017)

Diamond Logic Builder 15601 (Release Date: 12/14/2017)

- Resolve issue with the cruise indicator and battery warning lights with the LT Base Cluster

Diamond Logic Builder 15596 (Release Date: 12/4/2017)

- Force a reteach sequence after flashing Horizon cluster

Diamond Logic Builder 15595 (Release Date: 11/28/2017)

- Support programming of the HVAC module
- Support DTC clearing of the HVAC module
- Improve programming speeds for HMI modules

Improve programming status bar progress to better reflect overall progress

Diamond Logic Builder 15584 (Release Date: 08/25/2017)

- Reduce DTCs setting, when connecting to vehicle, with the key ON
- Additional graphics added for LT trucks

Diamond Logic Builder 15581 (Release Date: 06/22/2017)

- Resolved Body Controller, Real Time Clock offset, issue with Kernel 706.
- Resolved issue with displaying multiple Switch Pack modules under 'Detected Modules'
- Updated programming support for Switch Packs, Stalk Shifter, Cluster, and Light Control Module updates

Diamond Logic Builder 15577 (Release Date: 05/11/2017)

- Updated branding and DLB lcon
- Added link to change log site, from the help menu
- Added support for stalk shifter firmware updating
- Added support for additional warning lights on gen 2 cluster

Diamond Logic Builder Version 15573 (Release Date: 04/23/2017)

- Provides support for Horizon cluster diagnostics, mileage programming, and firmware updates
- Provides support for stalk shifter firmware updates
- Resolves simulator issues for 500K vehicles
- Resolves pin map naming issues
- Improves module detection and connection time

Diamond Logic Builder Version 15520 (Release Date: 1/5/2016)

Software Enhancements

- Added labeling for new hardware associated with the Gen 4 Body Controller

Diamond Logic Builder Version 15519 (Release Date: 8/25/2015)

Software Enhancements

Added 500K Emulator

Diamond Logic Builder Version 15518 (Release Date: 7/08/2015)

Software Fixes

- Resolved java null error on vehicles with VIS/VID

Diamond Logic Builder Version 15506 (Release Date: 4/6/2015)

Starting with Diamond Logic Builder version 15506, DLB includes a built-in version of Webstart. Software Fixes

- Signal Data Measurement
- Signal Recording closer to real time
- Cursor skip in Advanced Logic
- Interface cable icon and status message displayed.
- E-Fix, Support movement of physical items (Switches, Gauges, etc.)
- Graph Point Update Software Enhancements

- Diagnostics support for 250K and 500K
- Supports Gen4 VCM module (Program 748 Phase I launch)
- Built in webstart feature (no longer relies on Java webstart)
- Capture Java log

NOTE: After installation of version 15506, you MUST RE-SELECT YOUR INTERFACE CABLE from Tools > Select Com Link

© 2024 Navistar, Inc. All rights reserved. All marks are trademarks of their respective owners.